



# PHILIPPINE NOTICES TO MARINERS

**Edition No.: 06**  
**30 June 2018**

**Notices Nos.: 023 to 033**

---

## CONTENTS

- I Index of Charts Affected
  - II Notices to Mariners
  - III Corrections to Nautical Publications
  - IV Navigational Warnings
  - V Publication Notices
- 

Produced by the Hydrography Branch

Published by the  
Department of Environment and Natural Resources  
**NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY**

Notices to Mariners – Philippine edition are now on- line at  
***[http:// www.namria.gov.ph/download.php](http://www.namria.gov.ph/download.php)***

*Subscription may be requested thru e-mail at [icsu-hd@namria.gov.ph](mailto:icsu-hd@namria.gov.ph)*

**THE PHILIPPINE NOTICES TO MARINERS** is the monthly publication produced by the Hydrography Branch of the National Mapping and Resource Information Authority (NAMRIA). It contains the recent charts correction data, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format may be obtained by sending a request through e-mail address: [oss@namria.gov.ph](mailto:oss@namria.gov.ph) or by downloading at the NAMRIA website: [www.namria.gov.ph/download.php](http://www.namria.gov.ph/download.php).

Masters of vessels and other concerned are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots which may come to their attention to the **Director, Hydrography Branch**. If such information warrants urgent attention like for instance the non-existence of aids to navigation or failure of light beacons or similar structure or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:

Mail: NAMRIA-Hydrography Branch, 421 Barraca St., San Nicolas, 1010 Manila, Philippines  
E-mail: [oss@namria.gov.ph](mailto:oss@namria.gov.ph)  
Fax: (+632) 242-2090


The form at the back cover page of this publication must be used in reporting information on dangers to navigation, lighted aids, and other features that should be included in the nautical charts.

# Explanatory Notes

- The Philippine Notices to Mariners is divided to following sections:

**Section I. Index of Charts Affected** – Contains the list of all nautical charts which have been affected by Notices to Mariners and the notice numbers which have affected them.

**Section II-A. Notices to Mariners** - Contains corrections to nautical charts in sequential number with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:



Notice No. preceded by asterisk “ \* ” indicates that the information is based upon original Philippine source.

**Section II-B. Temporary & Preliminary Notices** – Contains Notices to Mariners that temporarily affects the nautical charts or have preliminary information that is subject to further verification. The capital “P” or “T” affixed in the number of any notice denotes “*preliminary*” or “*temporary*”, respectively.

A list of Temporary and Preliminary Notices that are still in force, as well as those that are canceled, is published in this publication every month. The list may be read on page iv.

**Section III-A. Corrections to List of Lights** – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contains updates will be denoted by an asterisk “ \* ”. All columns will be denoted by asterisks in the case of new lights.

This section is intended to be cut out and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from true the North 000° to 360°. Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should be forwarded to the Commandant of the Philippine Coast Guard.

**Section III-B. Coast Pilot Corrections** – Contains the corrections to the latest edition of the Philippine Coast Pilot book.

**Section IV. Navigational Warnings** – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

**Section V. Publication Notices** – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

2. NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that it may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard ship and use a lookout during navigation.
4. Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some navigational lights. Buoys and beacons are sometimes lost or destroyed specially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that due to the age and quality of some of information, such satellite-derived positions may be more accurate than charted details.

Nautical Charts, Topographic Maps, Tide and Current Tables and related publications are available for sale at the following NAMRIA Map Sales Offices (MSO):

**METRO MANILA:****NAMRIA Main Office MSO**

Fort Andres Bonifacio, Taguig City  
Contact Nos. (02) 810-4831 to 34 local 240,  
(02) 810-5467, 0919-298990

**Manila MSO**

Hydrography Branch  
421 Barraca Street, San Nicolas, Manila  
Contact Nos. (02) 241-3494 to 96 local 117,  
(02) 245-9498, 0919-6259276

**DENR Central Office MSO**

Forest Management Bureau (FMB) Compound  
Visayas Avenue, Quezon City  
Contact Nos. (02) 925-1157, 0915-5433557

**REGION I:****San Fernando (La Union) MSO**

DENR Government Center  
Sevilla, San Fernando City  
Contact Nos. (072) 700-7957, (072) 242-6201,  
0927-9187175

**REGION II:****Cagayan MSO**

DENR – LEP, Building II  
Carig, Tuguegarao City  
Contact Nos. (072) 700-7957, (072) 242-6201,  
0999-4086917

**CORDILLERA ADMINISTRATIVE REGION:****Baguio City MSO**

Cottage I Forester Compound,  
PACDAL, Baguio City  
Contact Nos. (074) 442-5429, (074) 442-4531,  
0918-9203590

**REGION III:****Nueva Ecija MSO**

GIS Room, WMRC Building,  
Central Luzon State University Compound  
Maharlika Highway, Muñoz City  
Contact Nos. (044) 456-0690, 0917-9313827

**Pampanga MSO**

Diosdado Macapagal Government Center  
Maimpis, San Fernando City  
Contact Nos. (045) 963-4650, (045) 963-4646 or 49,  
0910-3725623

**REGION IV-A:****Southern Tagalog MSO**

Provincial Planning and Development Office  
Laurel Park, Capitol Site, Batangas City  
Contact Nos. (043) 723-3286, 0919-9750907

**REGION IV-B:****Puerto Princesa MSO**

DENR-PENRO Compound,  
Brgy. Santa Monica, Puerto Princesa City  
Contact Nos. (048) 433-5638, (048) 433-5639,  
0928-7545363

**REGION V:****Legazpi City MSO**

DENR-Ecosystems Research and Dev't Service,  
Kalikasan Park, Anahaw Vill., Sagpon, Legazpi City  
Contact Nos. (052) 481-1515, (052) 481-1542,  
(052) 480-9825, 0920-4378877

**REGION VI:****Iloilo City MSO**

DENR – Forestry Building,  
Parola, Fort San Pedro, Iloilo City  
Contact Nos. (033) 336-5480, (033) 336-1013,  
0919-8873862

**REGION VII:****Cebu City MSO**

Room 301, Osmeña Bldg. II, Osmeña Blvd, Cebu City  
Contact Nos. (032) 505-9945, 0932-6418592

**REGION VIII:****Tacloban City MSO**

DENR Compound, Sto. Niño Extension, Tacloban City  
Contact Nos. (053) 325-6223, (053) 321-3386,  
0921-3628489

**REGION IX:****Zamboanga City MSO**

DENR CENRO West  
General Vicente Alvarez St., Zone 4, Zamboanga City  
Contact Nos. (062) 991-2149, (062) 992-2484,  
0935-8609439

**Zamboanga del Sur MSO**

4<sup>th</sup> floor Pantaran Building, Rizal Avenue,  
Balingasan District, Pagadian City  
Contact Nos. (062) 215-4065, 0907-2777422

**REGION X:****Cagayan de Oro City MSO**

Day Care Center Building, DENR-Compound,  
Macabalan (Puntod), Cagayan de Oro City  
Contact Nos. (088) 856-9050, (088) 856-9591,  
0926-4148976

**REGION XI:****Davao City MSO**

FRCD Building, DENR-Compound  
Lanang, Davao City  
Contact Nos. (082) 234-4401, (082) 234-7441,  
0915-6127770

**REGION XII:****Koronadal City MSO**

DENR Region 12, Land Evaluation Party Office,  
Aurora Street, Koronadal City, South Cotabato  
Contact Nos. (083) 228-8476, 0908-5459367,  
0998-9840921

**REGION XII:****Butuan City MSO**

Day Care Center Building, DENR Compound,  
Ambago, Butuan City, Agusan del Norte  
Contact Nos. (085) 342-6124, (085) 341-3250,  
0948-6209442, 0926-6835521

# **List of Temporary and Preliminary Notices**

(in force as of 30 June 2018)

06(032)P/18 – LUZON, W. COAST, San Fernando Harbor – Buoy

01(004)P/18 – SULU ARCHIPELAGO – Recommended Route

07(040)P/17 – MINDANAO, W. COAST, Moro Gulf – Recommended Route

02(014)P/17 – MINDANAO, N. COAST, Butuan Bay – Submarine Pipeline

## TABLE OF CONTENTS

Index of Charts Affected	1
Notices to Mariners	2
Temporary & Preliminary Notices	15
List of Lights Corrections	16
Coast Pilot Corrections	
Navigational Warnings	22
Publication Notices	39

**I****INDEX OF CHARTS AFFECTED**

<b>Charts No.</b>	<b>Notices Nos.</b>		<b>Charts No.</b>	<b>Notices Nos.</b>
1501	06(030)18		4429	06(028)18
1523	06(032)18		4429A	06(025)18
1536	06(024)18		4448	06(023)18
1537	06(026)18		4603	06(031)18
	06(027)18			
			4604	06(024)18
1546	06(023)18			
			4608	06(032)18
1548	06(028)18			
			4624	06(032)18
4208	06(033)P/18			
			4628	06(031)18
4209	06(033)P/18			
			4639	06(024)18
4211	06(030)18			
			4705	06(030)18
4212	06(029)18			
			4706	06(030)18
4213	06(029)18			
			4708	06(024)18
4246	06(033)P/18			06(031)18
				06(032)18
4255	06(030)18			
			4714	06(030)18
4416	06(023)18			
			4719	06(024)18
4425	06(026)18			06(031)18
	06(027)18			



## II NOTICES TO MARINERS

### \*06(023)18 – PANAY, SW. COAST, Iloilo Strait – Submarine Cable

Chart 1546 1Ed 02/02/2012 [WGS-84 Datum] Last NM 05(017)18


INSERT  joining: 10° 40.90' N., 122° 29.69' E.  
10° 40.70' N., 122° 29.74' E.  
10° 40.61' N., 122° 29.75' E.  
10° 40.55' N., 122° 29.76' E.  
10° 39.83' N., 122° 29.92' E.  
10° 39.11' N., 122° 30.15' E.  
10° 36.87' N., 122° 30.93' E.  
10° 36.57' N., 122° 31.23' E.  
10° 36.49' N., 122° 31.35' E.  
10° 36.32' N., 122° 31.69' E.  
10° 36.28' N., 122° 31.78' E.  
10° 36.27' N., 122° 31.80' E.

Chart 4416 2Ed 12/07/1992 [Luzon Datum] Last NM 05(017)18



INSERT  joining: 10° 40.97' N., 122° 29.60' E.  
10° 40.78' N., 122° 29.66' E.  
10° 40.68' N., 122° 29.67' E.  
10° 40.62' N., 122° 29.68' E.  
10° 39.90' N., 122° 29.83' E.  
10° 39.18' N., 122° 30.06' E.  
10° 36.94' N., 122° 30.84' E.  
10° 36.64' N., 122° 31.15' E.  
10° 36.56' N., 122° 31.26' E.  
10° 36.39' N., 122° 31.61' E.  
10° 36.35' N., 122° 31.69' E.  
10° 36.35' N., 122° 31.71' E.

Chart 4448 2Ed 08/30/2016 [WGS-84 Datum] Last NM 05(017)18

INSERT  joining: 10° 40.90' N., 122° 29.69' E.  
10° 40.70' N., 122° 29.74' E.  
10° 40.61' N., 122° 29.75' E.  
10° 40.55' N., 122° 29.76' E.  
10° 39.83' N., 122° 29.92' E.  
10° 39.11' N., 122° 30.15' E.  
10° 36.87' N., 122° 30.93' E.  
10° 36.57' N., 122° 31.23' E.  
10° 36.49' N., 122° 31.35' E.  
10° 36.32' N., 122° 31.69' E.  
10° 36.28' N., 122° 31.78' E.  
10° 36.27' N., 122° 31.80' E.


(PLDT; HD 123/18)

## II NOTICES TO MARINERS


### \*06(024)18 – MINDANAO, N. COAST, Camiguin Is. – Light

Chart 1536 1Ed 03/26/2018 [WGS-84 Datum] Last NM 05(020)18

INSERT  at: 09° 15.25' N., 124° 42.57' E.

 Cross at: 09° 12.41' N., 124° 37.97' E.


MOVE Mambajao Light  FI(2)6s13m7M from: 09° 15.32' N., 124° 42.95' E.  
to: 09° 15.22' N., 124° 43.22' E.


Farol Light  FI.5s10m from: 09° 04.92' N., 124° 46.18' E.  
to: 09° 05.05' N., 124° 46.90' E.


Catarman Light  FI(3)10s from: 09° 12.06' N., 124° 38.15' E.  
to: 09° 12.12' N., 124° 38.05' E.


Chart 4604 1Ed 04/30/1956 Rev 01/07/1985 [Luzon Datum] Last NM 03(006)18


INSERT  at: 09° 15.33' N., 124° 42.49' E.

 Cross at: 09° 12.4`8' N., 124° 37.89' E.

MOVE Binoni Light  FI.G.5s7M from: 09° 08.48' N., 124° 47.93' E.  
to: 09° 08.39' N., 124° 47.50' E.

Mambajao Light  FI(2)6s13m7M from: 09° 15.40' N., 124° 42.87' E.  
to: 09° 15.30' N., 124° 43.13' E.

Farol Light  FI.5s10m from: 09° 05.00' N., 124° 46.10' E.  
to: 09° 05.12' N., 124° 46.82' E.

Catarman Light  FI(3)10s from: 09° 12.13' N., 124° 38.07' E.  
to: 09° 12.19' N., 124° 37.97' E.

Continued to page 4.

## II NOTICES TO MARINERS

Continued from page 3.

Chart 4639 1Ed 10/30/1961 Rev 07/08/1985 [Luzon Datum] Last NM 08(049)17






MOVE Mambajao Light  FI(2)6s13m7M from: 09° 15' 24.0"N., 124° 42' 52.0"E.  
to: 09° 15' 18.1"N., 124° 43' 07.9"E.

Chart 4708 2Ed 11/2010 [WGS-84 Datum] Last NM 05(019)18

INSERT  at: 09° 15.3' N., 124° 42.6' E.


MOVE Binoni Light  FI.G.5s7M from: 09° 08.4' N., 124° 48.0' E.  
to: 09° 08.3' N., 124° 47.6' E.

Mambajao Light  FI(2)6s13m7M from: 09° 15.3' N., 124° 43.0' E.  
to: 09° 15.2' N., 124° 43.2' E.

Farol Light  FI.5s10m from: 09° 04.9' N., 124° 46.2' E.  
to: 09° 05.1' N., 124° 46.9' E.


Catarman Light  FI(3)10s from: 09° 12.1' N., 124° 38.2' E.  
to: 09° 12.1' N., 124° 38.1' E.

Chart 4719 1Ed 07/24/1961 Rev 02/12/1985 [Luzon Datum] Last NM 05(019)18

INSERT  at: 09° 15.3' N., 124° 42.5' E.

MOVE Binoni Light  FI.G.5s7M from: 09° 08.5' N., 124° 47.9' E.  
to: 09° 08.4' N., 124° 47.5' E.

Mambajao Light  FI(2)6s13m7M from: 09° 15.4' N., 124° 42.9' E.  
to: 09° 15.3' N., 124° 43.1' E.

Farol Light  FI.5s10m from: 09° 05.0' N., 124° 46.1' E.  
to: 09° 05.1' N., 124° 46.8' E.


Catarman Light  FI(3)10s from: 09° 12.1' N., 124° 38.1' E.  
to: 09° 12.2' N., 124° 38.0' E.


(NAMRIA Research Reports; HD 105/18, 106/18, 107/18, & 108/18)


## II NOTICES TO MARINERS


### \*06(025)18 – BOHOL, SW. COAST, Tagbilaran Port - Buoy


Chart 4429A 2Ed 02/26/2016 [WGS-84 Datum] Last NM 10(238)16

INSERT  *FI(2)G.5s* at: 09° 39' 16.0"N., 123° 50' 05.8"E.  
"1"

 *FI(2)R.5s* at: 09° 39' 25.7"N., 123° 49' 38.0"E.  
"2"

 *FI(2)G.5s* at: 09° 39' 10.4"N., 123° 50' 26.6"E.  
"3"

 *FI(2)R.5s* at: 09° 38' 59.8"N., 123° 50' 25.1"E.  
"4"


 *FI(2)G.5s* at: 09° 39' 02.1"N., 123° 50' 49.8"E.  
"5"


 *FI(2)R.5s* at: 09° 38' 43.6"N., 123° 50' 40.4"E.  
"6"


(PCG NM No. 102 of 2018; HD 104/18)


### \*06(026)18 – BOHOL, SE. COAST, Jagna Bay - Buoy

Chart 1537 1Ed 03/31/2011 [WGS-84 Datum] Last NM 04(012)18

INSERT  *FI(2)G.5s* at: 09° 38.55' N., 124° 22.15' E.  
"1"

 *FI(2)R.5s* at: 09° 38.79' N., 124° 22.43' E.  
"2"

 *FI(2)G.5s* at: 09° 38.76' N., 124° 22.02' E.  
"3"


 *FI(2)R.5s* at: 09° 38.90' N., 124° 22.22' E.  
"4"


Continued to page 6.

## II NOTICES TO MARINERS


Continued from Page 5.

Chart 4425 2Ed 12/07/1992 [Luzon Datum] Last NM 11(274)15

INSERT  Fl(2)G.5s at: 09° 38.63' N., 124° 22.06' E.  
"1"

 Fl(2)R.5s at: 09° 38.87' N., 124° 22.34' E.  
"2"


 Fl(2)G.5s at: 09° 38.84' N., 124° 21.94' E.  
"3"


 Fl(2)R.5s at: 09° 38.98' N., 124° 22.14' E.  
"4"

(PCG NM No. 102 of 2018; HD 104/18)


### \*06(027)18 – BOHOL, NE. COAST, Basiao Channel - Buoy

Chart 1537 1Ed 03/31/2011 [WGS-84 Datum] Last NM 04(012)18


INSERT  Fl(2)G.5s at: 10° 02.80' N., 124° 33.15' E.  
"1"

 Fl(2)R.5s at: 10° 03.05' N., 124° 33.12' E.  
"2"

 Fl(2)G.5s at: 10° 02.65' N., 124° 32.71' E.  
"3"

 Fl(2)R.5s at: 10° 02.90' N., 124° 32.78' E.  
"4"

 Fl(2)G.5s at: 10° 02.65' N., 124° 32.37' E.  
"5"


 Fl(2)R.5s at: 10° 02.88' N., 124° 32.50' E.  
"6"


Continued to page 7.


## II NOTICES TO MARINERS

Continued from Page 6.

Chart 1537 1Ed 03/31/2011 [WGS-84 Datum] Last NM 04(012)18

INSERT  *Fl(2)G.5s* at: 10° 02.75' N., 124° 32.10' E.  
"7"

 *Fl(2)R.5s* at: 10° 02.96' N., 124° 32.28' E.  
"8"

 *Fl(2)G.5s* at: 10° 02.98' N., 124° 31.84' E.  
"9"






 *Fl(2)R.5s* at: 10° 03.19' N., 124° 32.03' E.  
"10"


Chart 4425 2Ed 12/07/1992 [Luzon Datum] Last NM 11(274)15


INSERT  *Fl(2)G.5s* at: 10° 02.87' N., 124° 33.07' E.  
"1"


 *Fl(2)R.5s* at: 10° 03.13' N., 124° 33.03' E.  
"2"


 *Fl(2)G.5s* at: 10° 02.73' N., 124° 32.62' E.  
"3"

 *Fl(2)R.5s* at: 10° 02.98' N., 124° 32.70' E.  
"4"

 *Fl(2)G.5s* at: 10° 02.72' N., 124° 32.29' E.  
"5"

 *Fl(2)R.5s* at: 10° 02.96' N., 124° 32.41' E.  
"6"

 *Fl(2)G.5s* at: 10° 02.83' N., 124° 32.01' E.  
"7"


 *Fl(2)R.5s* at: 10° 03.04' N., 124° 32.19' E.  
"8"


Continued to page 8.

## II NOTICES TO MARINERS

Continued from Page 7.

Chart 4425 2Ed 12/07/1992 [Luzon Datum] Last NM 11(274)15


INSERT  *Fl(2)G.5s* at: 10° 03.06' N., 124° 31.76' E.  
"9"


 *Fl(2)R.5s* at: 10° 03.27' N., 124° 31.95' E.  
"10"


(PCG NM No. 102 of 2018; HD 104/18)


### \*06(028)18 – BOHOL, NW. COAST, Tubigon - Buoy


Chart 1548 1Ed 05/17/2017 [WGS-84 Datum] 12(070)17


INSERT  *Fl(2)G.5s* at: 10° 03.91' N., 123° 55.08' E.  
"1"


 *Fl(2)R.5s* at: 10° 03.68' N., 123° 54.69' E.  
"2"


 *Fl(2)G.5s* at: 10° 03.44' N., 123° 55.21' E.  
"3"


 *Fl(2)R.5s* at: 10° 03.23' N., 123° 54.85' E.  
"4"

 *Fl(2)G.5s* at: 10° 02.93' N., 123° 55.38' E.  
"5"

 *Fl(2)R.5s* at: 10° 02.70' N., 123° 55.08' E.  
"6"

 *Fl(2)G.5s* at: 10° 02.47' N., 123° 55.69' E.  
"7"

 *Fl(2)R.5s* at: 10° 02.25' N., 123° 55.40' E.  
"8"


 *Fl(2)G.5s* at: 10° 01.86' N., 123° 56.35' E.  
"9"


Continued to Page 9.


## II NOTICES TO MARINERS


Continued from Page 8.


Chart 1548 1Ed 05/17/2017 [WGS-84 Datum] 12(070)17


INSERT  FI(2)R.5s at: 10° 01.69' N., 123° 56.04' E.  
"10"


 FI(2)G.5s at: 10° 01.19' N., 123° 56.72' E.  
"11"


 FI(2)R.5s at: 10° 01.14' N., 123° 56.34' E.  
"12"


 FI(2)G.5s at: 09° 58.28' N., 123° 57.31' E.  
"13"


 FI(2)R.5s at: 09° 58.22' N., 123° 56.85' E.  
"14"


 FI(2)G.5s at: 09° 57.80' N., 123° 57.44' E.  
"15"

 FI(2)R.5s at: 09° 57.63' N., 123° 57.05' E.  
"16"

 VQ(9)10s at: 10° 00.54' N., 123° 56.81' E.  
"A"

 VQ(3)5s at: 10° 00.12' N., 123° 56.85' E.  
"B"

 VQ(9)10s at: 09° 59.72' N., 123° 57.14' E.  
"C"

 VQ(9)10s at: 09° 59.24' N., 123° 57.18' E.  
"D"


Continued to Page 10.





## II NOTICES TO MARINERS


Continued from Page 9.


Chart 4429 1Ed 24/07/1961 Rev 13/07/1987 [Luzon Datum] Last NM 12(070)17


INSERT  FI(2)G.5s at: 10° 03.99' N., 123° 55.00' E.  
G "1"


 FI(2)R.5s at: 10° 03.75' N., 123° 54.61' E.  
R "2"


 FI(2)G.5s at: 10° 03.51' N., 123° 55.13' E.  
G "3"


 FI(2)R.5s at: 10° 03.30' N., 123° 54.77' E.  
R "4"

 FI(2)G.5s at: 10° 03.00' N., 123° 55.30' E.  
G "5"


 FI(2)R.5s at: 10° 02.78' N., 123° 54.99' E.  
R "6"


 FI(2)G.5s at: 10° 02.55' N., 123° 55.61' E.  
G "7"


 FI(2)R.5s at: 10° 02.33' N., 123° 55.32' E.  
R "8"

 FI(2)G.5s at: 10° 01.94' N., 123° 56.27' E.  
G "9"

 FI(2)R.5s at: 10° 01.77' N., 123° 55.95' E.  
R "10"

 FI(2)G.5s at: 10° 01.26' N., 123° 56.63' E.  
G "11"

 FI(2)R.5s at: 10° 01.22' N., 123° 56.25' E.  
R "12"


 FI(2)G.5s at: 09° 58.36' N., 123° 57.23' E.  
G "13"


Continued to page 11.


## II NOTICES TO MARINERS


Continued from Page 10.


Chart 4429 1Ed 24/07/1961 Rev 13/07/1987 [Luzon Datum] Last NM 12(070)17


INSERT  FI(2)R.5s at: 09° 58.30' N., 123° 56.77' E.  
R "14"


 FI(2)G.5s at: 09° 57.87' N., 123° 57.36' E.  
G "15"

 FI(2)R.5s at: 09° 57.71' N., 123° 56.97' E.  
R "16"

 VQ(9)10s at: 10° 00.62' N., 123° 56.73' E.  
"A"  
YBY

 VQ(3)5s at: 10° 00.19' N., 123° 56.76' E.  
"B"  
BYB


 VQ(9)10s at: 09° 59.80' N., 123° 57.06' E.  
"C"  
YBY


 VQ(9)10s at: 09° 59.32' N., 123° 57.10' E.  
"D"  
YBY

(PCG NM No. 102 of 2018; HD 104/18)

### \*06(029)18 – LUZON, W. COAST, Subic Bay – Buoy

Chart 4212 1Ed 03/07/2005 [WGS-84 Datum] Last NM 05(018)18

DELETE  FI(2)G.4s4M at: 14° 46.97' N., 120° 12.43' E.  
G

 Iso.2s4M at: 14° 46.78' N., 120° 12.80' E.  
RW



 FI.R.4s4M at: 14° 48.44' N., 120° 15.57' E.  
R

Chart 4213 1Ed 03/2006 [WGS-84 Datum] Last NM 05(018)18

DELETE  FI.R.4s4M at: 14° 48.44' N., 120° 15.57' E.  
R

(SBMA; HD 140/18)

## II NOTICES TO MARINERS

### **\*06(030)18 – LUZON, W. COAST, Manila Bay – Light**

Chart 1501 1Ed 02/02/2012 [WGS-84 Datum] 05(022)18

AMEND characteristics of Corregidor Island Light from FI(3)20s193m23M to  
FI.5s193m23M at: 14° 22.77' N., 120° 34.62' E.

Chart 4211 1Ed 06/20/1960 Rev 01/12/1981 [Luzon Datum] Last NM 06(036)17

AMEND characteristics of Corregidor Island Light from FI(3)20s193m23M to  
FI.5s193m23M at: 14° 22.87' N., 120° 34.53' E.

Chart 4255 2Ed 01/06/1975 Rev 06/17/1985 [Luzon Datum] Last NM 05(022)18

AMEND characteristics of Corregidor Island Light from FI(3)20s193m23M to  
FI.5s193m23M at: 14° 22.87' N., 120° 34.53' E.

Chart 4705 3Ed 03/2010 [WGS84 Datum] Last NM 09(054)17

AMEND characteristics of Corregidor Island Light from FI(3)20s193m23M to  
FI.5s193m23M at: 14° 22.8' N., 120° 34.6' E.

Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 04(014)18

AMEND characteristics of Corregidor Island Light from FI(3)20s193m23M to  
FI.5s193m23M at: 14° 22.8' N., 120° 34.6' E.

Chart 4714 1Ed 09/14/1959 Rev 03/31/1986 [Luzon Datum] Last NM 04(014)18

AMEND characteristics of Corregidor Island Light from FI(3)20s193m23M to  
FI.5s193m23M at: 14° 22.9' N., 120° 34.5' E.

(PCG NM No. 148 of 2018; HD 154/18)

## II NOTICES TO MARINERS

### \*06(031)18 – MINDANAO, NE. COAST, Tandag – Light

Chart 4603 1Ed 09/22/1958 Rev 09/08/1975 [Luzon Datum] Last NM 05(020)18

AMEND characteristics of Maboia Light from FI(2)15s to FI(2)10s  
at: 09° 05.20' N., 126° 11.92' E.

Chart 4628 1Ed 05/26/1958 Rev 07/26/1976 [Luzon Datum] Last NM 01(004)16

AMEND characteristics of Maboia Light from FI(2)15s to FI(2)10s  
at: 09° 05.20' N., 126° 11.92' E.

Chart 4708 2Ed 11/2010 [WGS-84 Datum] Last NM 05(019)18

AMEND characteristics of Maboia Light from FI(2)15s to FI(2)10s  
at: 09° 05.1' N., 126° 12.0' E.

Chart 4719 1Ed 07/24/1961 Rev 02/12/1985 [Luzon Datum] Last NM 05(020)18

AMEND characteristics of Maboia Light from FI(2)15s to FI(2)10s  
at: 09° 05.2' N., 126° 11.9' E.

(PCG NM No. 139 of 2018; HD 154/18)

## II NOTICES TO MARINERS

### \*06(032)18 – MINDANAO, SE. COAST, Davao Gulf – Light

Chart 1523 1Ed 06/28/2017 [WGS-84 Datum] Last NM 04(015)18


MOVE Talicud Light  Fl.5s10M from: 06° 54.47' N., 125° 41.39' E.  
to: 06° 54.45' N., 125° 41.26' E.

Chart 4608 1Ed 11/04/1968 Rev 10/06/1980 [Luzon Datum] Last NM 12(259)16


MOVE Talicud Light  Fl.5s10M from: 06° 54.55' N., 125° 41.30' E.  
to: 06° 54.53' N., 125° 41.17' E.

Chart 4624 2Ed 12/02/1991 [Luzon Datum] Last NM 04(015)18


MOVE Talicud Light  Fl.5s10M from: 06° 54.55' N., 125° 41.30' E.  
to: 06° 54.53' N., 125° 41.17' E.

Chart 4708 2Ed 11/2010 [WGS-84 Datum] Last NM 05(019)18

MOVE Talicud Light  Fl.5s10M from: 06° 54.5' N., 125° 41.4' E.  
to: 06° 54.5' N., 125° 41.3' E.

(PCG NM No. 114 of 2018; HD 111/18)

## II TEMPORARY & PRELIMINARY NOTICES

### \*06(033)P/18 – LUZON, W. COAST, San Fernando Harbor – Buoy

1. Shell Philippines Corp. recently installed the following lighted buoys:

Buoy Name	Position (WGS-84 Datum)
Port Hand Marked Lighted Buoy Nr. 1	16° 38' 17"N., 120° 17' 59"E.
Port Hand Marked Lighted Buoy Nr. 2	16° 38' 10"N., 120° 17' 37"E.
Port Hand Marked Lighted Buoy Nr. 3	16° 37' 59"N., 120° 18' 06"E.

Charts affected: 4208, 4209, & 4246.  
(PCG NM No. 147 of 2018; HD 155/18)

### III

## LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)
<b>REGION III – CENTRAL LUZON</b>							
<b>ZAMBALES</b>							
0706	Main Traffic Lane Center Lighted Buoy					DELETED from the List of Lights	06/18
0707	Main Traffic Lane West Lighted Buoy					DELETED from the List of Lights	06/18
0722	Main Traffic Lane East Lighted Buoy					DELETED from the List of Lights	06/18
<b>REGION IV-A – CALABARZON</b>							
<b>CAVITE</b>							
0045	F2634	<b>CORREGIDOR ISLAND</b>	14 22 52 N 120 34 32 E	FI W 5s	193	<b>23</b> Concrete, white round tower on white dwelling, 15	Vis 192°-110°(278°) 06/18
				*			
<b>QUEZON</b>							
0076	F2602	PISNGI	13 53 51 N 121 36 04 E	FI(2)W 5s		10	White concrete tower, 9 Vis 294°-027°(93°) 06/18 <b>TE 2018</b> *
0079	F2596	GENERAL LUNA	13 41 15 N 122 10 10 E	FI W 5s	15	7	Concrete <b>TE 2018</b> 06/18 *
0595	F2503.75	SAN FRANCISCO	13 20 45 N 122 30 50 E	FI W 5s			Concrete <b>TE 2018</b> 06/18 *
<b>REGION VII – CENTRAL VISAYAS</b>							
<b>BOHOL</b>							
	LPM–Tag Buoy 1	09 39 16 N 123 50 06 E	FI(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder *	Lateral Port Hand Mark 06/18 In WGS-84 Datum *
	*	*	*				
	LSM–Tag Buoy 2	09 39 26 N 123 49 38 E	FI(2)R 5s			Red conical buoy. Topmark: single cone pointing upward *	Lateral Starboard Hand Mark 06/18 In WGS-84 Datum *
	*	*	*				
	LPM–Tag Buoy 3	09 39 10 N 123 50 27 E	FI(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder *	Lateral Port Hand Mark 06/18 In WGS-84 Datum *
	*	*	*				
	LSM–Tag Buoy 4	09 39 00 N 123 50 25 E	FI(2)R 5s			Red conical buoy. Topmark: single cone pointing upward *	Lateral Starboard Hand Mark 06/18 In WGS-84 Datum *
	*	*	*				
	LPM–Tag Buoy 5	09 39 02 N 123 50 50 E	FI(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder *	Lateral Port Hand Mark 06/18 In WGS-84 Datum *
	*	*	*				

Note: Asterisk “ \* ” indicates new information in the column above it.

### III

## LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)
<b>REGION VII – CENTRAL VISAYAS</b>							
<b>BOHOL</b>							
	<i>LSM–Tag Buoy 6</i>	09 38 44 N 123 50 40 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–J Buoy 1</i>	09 38 33 N 124 22 09 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–J Buoy 2</i>	09 38 47 N 124 22 26 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–J Buoy 3</i>	09 38 46 N 124 22 01 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–J Buoy 4</i>	09 38 54 N 124 22 13 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tap Buoy 1</i>	10 02 48 N 124 33 09 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tap Buoy 2</i>	10 03 03 N 124 33 07 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tap Buoy 3</i>	10 02 39 N 124 32 42 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tap Buoy 4</i>	10 02 54 N 124 32 47 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tap Buoy 5</i>	10 02 39 N 124 32 22 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*

Note: Asterisk “ \* ” indicates new information in the column above it.



### III

## LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)
<b>REGION VII – CENTRAL VISAYAS</b>							
<b>BOHOL</b>							
	<i>LSM–Tap Buoy 6</i>	10 02 53 N 124 32 30 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tap Buoy 7</i>	10 02 45 N 124 32 06 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tap Buoy 8</i>	10 02 58 N 124 32 17 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tap Buoy 9</i>	10 02 59 N 124 31 51 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tap Buoy 10</i>	10 03 11 N 124 32 02 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tu Buoy 1</i>	10 03 55 N 123 55 05 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tu Buoy 2</i>	10 03 41 N 123 54 41 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tu Buoy 3</i>	10 03 26 N 123 55 13 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tu Buoy 4</i>	10 03 14 N 123 54 51 E	Fl(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tu Buoy 5</i>	10 02 56 N 123 55 23 E	Fl(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*

Note: Asterisk “ \* ” indicates new information in the column above it.

### III

## LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)
<b>REGION VII – CENTRAL VISAYAS</b>							
<b>BOHOL</b>							
	<i>LSM–Tu Buoy 6</i>	10 02 42 N 123 55 05 E	FI(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tu Buoy 7</i>	10 02 28 N 123 55 42 E	FI(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tu Buoy 8</i>	10 02 15 N 123 55 24 E	FI(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tu Buoy 9</i>	10 01 52 N 123 56 21 E	FI(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tu Buoy 10</i>	10 01 42 N 123 56 02 E	FI(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tu Buoy 11</i>	10 01 11 N 123 56 43 E	FI(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tu Buoy 12</i>	10 01 08 N 123 56 20 E	FI(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tu Buoy 13</i>	09 58 17 N 123 57 18 E	FI(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tu Buoy 14</i>	09 58 13 N 123 56 51 E	FI(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LPM–Tu Buoy 15</i>	09 57 48 N 123 57 26 E	FI(2)G 5s			Green cylindrical buoy. Topmark: single green cylinder	Lateral Port Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*
	<i>LSM–Tu Buoy 16</i>	09 57 38 N 123 57 03 E	FI(2)R 5s			Red conical buoy. Topmark: single cone pointing upward	Lateral Starboard Hand Mark In WGS-84 Datum 06/18
	*	*	*			*	*

Note: Asterisk “\*” indicates new information in the column above it.

### III

## LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)	
<b>REGION VII – CENTRAL VISAYAS</b>								
<b>BOHOL</b>								
	<i>WCM–Tu Buoy A</i>	10 00 33 N 126 56 49 E	VQ(9)10s			Yellow with horizontal black band. Topmark: top cone pointing downward and bottom cone pointing upward.	West Cardinal Mark In WGS-84 <sup>06/18</sup> Datum	
	*	*	*			*	*	
	<i>ECM–Tu Buoy B</i>	10 00 07 N 123 56 51 E	VQ(3)5s			Black with horizontal yellow band. Topmark: top cone pointing upward and bottom cone pointing downward.	East Cardinal Mark <sup>06/18</sup> In WGS-84 Datum	
	*	*	*			*	*	
	<i>WCM–Tu Buoy C</i>	09 59 43 N 123 57 08 E	VQ(9)10s			Yellow with horizontal black band. Topmark: top cone pointing downward and bottom cone pointing upward.	West Cardinal Mark In WGS-84 <sup>06/18</sup> Datum	
	*	*	*			*	*	
	<i>WCM–Tu Buoy D</i>	09 59 14 N 123 57 11 E	VQ(9)10s			Yellow with horizontal black band. Topmark: top cone pointing downward and bottom cone pointing upward.	West Cardinal Mark In WGS-84 <sup>06/18</sup> Datum	
	*	*	*			*	*	
<b>REGION X – NORTHERN MINDANAO</b>								
<b>CAMIGUIN</b>								
0354	F2262	MAMBAJAO	09 15 13 N 124 43 13 E	FI(2)W 6s	13	7	White concrete tower, 12	In WGS-84 Datum <sup>06/18</sup> *
0355	F2263	BINONI	09 08 18 N 124 47 35 E	FI G 5s		7		In WGS-84 Datum <sup>06/18</sup> *
0624	F2263.5	FAROL	09 05 03 N 124 46 54 E	FI W 5s	10		White steel and GRP, 10	In WGS-84 <sup>06/18</sup> Datum *
0729	F2261.9	CATARMAN	09 12 07 N 124 38 03 E	FI(3)W 10s			White tower	In WGS-84 <sup>06/18</sup> Datum *

Note: Asterisk “ \* ” indicates new information in the column above it.

### III

## LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)
<b>REGION XI – DAVAO REGION</b>							
<b>DAVAO del NORTE</b>							
0398	F2232	TALICUD	06 54 27 N 124 41 16 E	FI W 5s	10	White concrete tower	In WGS-84 Datum 06/18
	*	*				*	*
<b>REGION XIII – CARAGA</b>							
<b>SURIGAO del SUR</b>							
0406	F2243.5	MABOA	09 05 07 N 126 12 01 E	FI(2)W 10s		GRP	In WGS-84 Datum 06/18
		*		*			*

Note: Asterisk “\*” indicates new information in the column above it.

## **IV NAVIGATIONAL WARNINGS**

Date: 09 June 2017

Reference: PCG NTM 099-2017 (HD 102/17)

### MESSAGE

**NAVPHIL 065/17–CEBU, E. COAST, MANDAUE, CEBU–REPAIR/REHABILITATION**

**THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS (DPWH) IS CURRENTLY CONDUCTING REPAIR/REHABILITATION OF PIER FOOTING NUMBER 7 AND PIER FOOTING NUMBER 8 OF OLD MANDAUE-MACTAN BRIDGE WHICH STARTED LAST 10 MAY 2017 AND IS ESTIMATED TO BE COMPLETED BY DECEMBER 2018. THE REPAIR ACTIVITIES WILL BE CONDUCTED AT THE FOLLOWING COORDINATES:**

<b>BRIDGE PIER FOOTING NO. 7</b>	<b>10° 19' 13"N., 123° 57' 19"E.</b>
<b>BRIDGE PIER FOOTING NO. 8</b>	<b>10° 19' 09"N., 123° 57' 21"E.</b>

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.**

## **IV NAVIGATIONAL WARNINGS**

Date: 10 October 2017

Reference: PCG NTM 204-2017 (HD 186/17)

### MESSAGE

**NAVPHIL 106/17 – MINDANAO, N. COAST, ILIGAN BAY – PIER CONSTRUCTION**

**BARGE HANG ZHUANG Q1, WILL CONSTRUCT A POWER PLANT'S PIER IN KAUSWAGAN, LANA DEL NORTE FROM 23 SEPTEMBER 2017 TO 22 SEPTEMBER 2018, IN THE VICINITY OF THE FOLLOWING COORDINATES:**

**08° 11' 23"N., 124° 06' 53"E.**

**ALL SHIPS/WATERCRAFTS TRANSITING ALONG THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO OBSERVE SAFE DISTANCE FROM THE VESSEL AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**

**IV**  
**NAVIGATIONAL WARNINGS**

Date: 23 March 2018

Reference: PCG NTM 062-2018 (HD 055/18)

**MESSAGE**

---

**NAVPHIL 036/18 – LUZON, W. COAST, PASIG RIVER – CONSTRUCTION WORKS**

**DUMDUMA CONTRUCTION AND TRADING CORP. IS CONSTRUCTING THE SAN JUAN RIVER VIADUCT FROM 05 MARCH 2018 TO 31 DECEMBER 2019 WITHIN THE VICINITY OF THE FOLLOWING COORDINATES:**

**14° 35' 26.63"N., 121° 00' 49.67"E.**

**14° 35' 23.39"N., 121° 00' 50.40"E.**

**14° 35' 23.15"N., 121° 00' 51.12"E.**

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**

**IV**  
**NAVIGATIONAL WARNINGS**

Date: 04 May 2018

Reference: PCG NTM 090-2018 (HD 080/18)

**MESSAGE**

---

**NAVPHIL 052/18 – PALAWAN, N.E. COAST, MALAMPAYA GAS FIELD –  
OFFSHORE ACTIVITY**

**PHILODRILL CORP., UTILIZING MV ENA HABITAT, WILL  
PERFORM WELL PLUG AND ABANDON CAMPAIGN ACTIVITIES FOR  
APPROXIMATELY TWO (2) MONTHS DURATION STARTING ON 06 MAY  
2018, AT THIS POSITION:**

**11° 25.817'N., 119° 03.726'E.**

**ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE  
ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE  
INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT  
ALL TIMES.**



## **IV**

# **NAVIGATIONAL WARNINGS**

Date: 22 May 2018

Reference: PCG NTM 115-2018 (HD 115/18)

### MESSAGE

#### **NAVPHIL 059/18 – LUZON W. COAST, BACOR BAY – BATHYMETRIC SURVEY**

**EGS ASIA INC., IS CONDUCTING BATHYMETRIC SINGLE-BEAM ECHO SOUNDING SURVEY (SBES) AND METOCEAN STUDY AT PROPOSED BACOR RECLAMATION AND DEVELOPMENT PROJECT AT BACOR CITY, CAVITE FROM 21 MAY 2018 TO 30 JULY 2018 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

<b>Point</b>	<b>Latitude</b>	<b>Longitude</b>
<b>1</b>	<b>14° 28' 46.62"N.</b>	<b>120° 55' 15.30"E.</b>
<b>2</b>	<b>14° 27' 40.38"N.</b>	<b>120° 55' 36.42"E.</b>
<b>3</b>	<b>14° 27' 46.92"N.</b>	<b>120° 56' 46.44"E.</b>
<b>4</b>	<b>14° 28' 09.30"N.</b>	<b>120° 57' 36.30"E.</b>
<b>5</b>	<b>14° 28' 30.24"N.</b>	<b>120° 58' 01.80"E.</b>
<b>6</b>	<b>14° 29' 32.58"N.</b>	<b>120° 57' 37.08"E.</b>

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**

## **IV**

# **NAVIGATIONAL WARNINGS**

Date: 28 May 2018

Reference: NAMRIA (HD 117/18)

### MESSAGE

**NAVPHIL 061/18 – LUZON W. COAST, MANILA BAY– HYDROGRAPHIC SURVEY**

**THE NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY (NAMRIA) HYDROGRAPHY BRANCH, UTILIZING BRP HYDROGRAPHER PALMA IS CONDUCTING HYDROGRAPHIC SURVEY ACTIVITIES FROM 23 MAY 2018 UNTIL 31 JULY 2018 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

**A: 14° 42' 40"N., 120° 45' 17"E.  
B: 14° 38' 05"N., 120° 45' 18"E.  
C: 14° 35' 16"N., 120° 50' 04"E.  
D: 14° 30' 41"N., 120° 51' 21"E.  
E: 14° 25' 35"N., 120° 45' 04"E.  
F: 14° 16' 57"N., 120° 38' 35"E.  
G: 14° 30' 29"N., 120° 54' 04"E.  
H: 14° 30' 43"N., 120° 57' 25"E.  
I: 14° 32' 57"N., 120° 57' 19"E.  
J: 14° 36' 26"N., 120° 54' 57"E.  
K: 14° 40' 59"N., 120° 50' 23"E.**

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**

## **IV**

# **NAVIGATIONAL WARNINGS**

Date: 29 May 2018

Reference: PCG NTM 117-2018 (HD 119/18)

### MESSAGE

**NAVPHIL 063/18 – LUZON, W. COAST, MANILA BAY – DRILLING WORKS**

**THE GEOTECHNICS PHILIPPINES INC., WILL CONDUCT GEOTECHNICAL INVESTIGATION AND DRILLING WORKS FOR THE PROPOSED SANGLEY INTERNATIONAL AIRPORT IN CAVITE CITY FROM 01 JUNE 2018 TO 15 JULY 2018 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

**14° 26' 56.580"N., 120° 52' 35.868"E.  
14° 28' 07.680"N., 120° 51' 33.048"E.  
14° 28' 25.356"N., 120° 51' 54.864"E.  
14° 29' 30.228"N., 120° 50' 58.920"E.  
14° 31' 45.372"N., 120° 53' 44.052"E.  
14° 29' 41.856"N., 120° 55' 30.864"E.  
14° 28' 54.768"N., 120° 55' 12.720"E.**

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**

# IV

## NAVIGATIONAL WARNINGS

Date: 06 June 2018

Reference: PCG NTM 123-2018 (HD 131/18)

### MESSAGE

---

#### NAVPHIL 067/18 – PHILIPPINE SEA – CABLE ROUTE SURVEY

EGS ASIA LTD., UTILIZING RV NORTHERN ENDEAVOR, WILL CONDUCT A CABLE ROUTE SURVEY FROM DAET, CAMARINES NORTE AND THE PHILIPPINE SEA FROM 04-21 JUNE 2018 WITHIN THE ROUTE DEFINED BY THE FOLLOWING COORDINATES:

1	16° 46' 30.56"N.	127° 39' 32.04"E.
2	16° 15' 41.09"N.	126° 55' 42.49"E.
3	15° 33' 08.80"N.	125° 55' 25.06"E.
4	15° 17' 03.71"N.	125° 32' 40.52"E.
5	15° 00' 09.66"N.	124° 44' 26.82"E.
6	15° 00' 07.67"N.	124° 44' 22.78"E.
7	14° 57' 57.84"N.	124° 39' 58.93"E.
8	14° 44' 12.98"N.	124° 12' 03.63"E.
9	14° 37' 18.53"N.	123° 58' 02.56"E.
10	14° 29' 26.06"N.	123° 42' 04.28"E.
11	14° 21' 33.33"N.	123° 26' 06.07"E.
12	14° 16' 20.68"N.	123° 15' 32.63"E.
13	14° 09' 41.75"N.	123° 02' 04.75"E.
14	14° 08' 24.06"N.	123° 00' 22.78"E.
15	14° 08' 22.04"N.	123° 00' 15.43"E.
16	14° 08' 16.25"N.	122° 59' 54.30"E.
17	14° 08' 22.36"N.	122° 59' 15.81"E.
18	14° 08' 25.78"N.	122° 58' 54.30"E.
19	14° 08' 25.92"N.	122° 58' 53.45"E.
20	14° 08' 25.44"N.	122° 58' 51.30"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

## **IV**

# **NAVIGATIONAL WARNINGS**

Date: 07 June 2018

Reference: NAMRIA (HD 132/18)

### MESSAGE

**NAVPHIL 068/18 – GUIMARAS, NW. COAST, ILOILO STRAIT – TIDAL SURVEY**

**THE NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY (NAMRIA) HYDROGRAPHY BRANCH, IS DEPLOYING CURRENT METERS, WHICH ARE MARKED BY ORANGE COLORED BUOYS, FROM 07-08 JUNE 2018 AT THE FOLLOWING POSITIONS:**

**SITE 1:        10° 40' 08.4"N., 122° 35' 18.7"E.**  
**SITE 2:        10° 39' 00.8"N., 122° 33' 37.2"E.**  
**SITE 3:        10° 38' 29.5"N., 122° 33' 20.4"E.**

**THE CURRENT METERS AND BUOYS WILL BE RETRIEVED AFTER 30 DAYS OR UNTIL 08 JULY 2018.**

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**

## **IV**

# **NAVIGATIONAL WARNINGS**

Date: 14 June 2018

Reference: Letter of Blue Horizon Shipping (HD 136/18)

### **MESSAGE**

---

**NAVPIL 074/18 – LUZON, W. COAST, MANILA BAY – DREDGING**

**BLUE HORIZON SHIPPING & LOGISTICS SERVICES INC., UTILIZING HOPPER BARGE YUE QING YUAN HUO 6170, DREDGER BARGE YUE GONG BO 34 AND DREDGER BARGE YUE GUANG ZHOU GONG 0233, IS CONDUCTING DREDGING WORK FROM 08 JUNE 2018 TO 09 JULY 2018 AT THE CAVITE GATEWAY TERMINAL (CGT) IN TANZA, CAVITE AT THE FOLLOWING COORDINATES:**

**14° 21' 52" N., 120° 46' 52" E.**

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**

# IV

## NAVIGATIONAL WARNINGS

Date: 21 June 2018

Reference: Seabird Ship Management Letter (HD 141/18)

### MESSAGE

---

**NAVPHIL 076/18 – LUZON, W. COAST, MANILA BAY – HYDROGRAPHIC SURVEY  
AND SOIL SAMPLING**

**UNITED SURVEYORS PTE. LTD., UTILIZING MTUG CHRISTIANSEN VI AND  
MOTOR LAUNCH SAN JOSE ONE, WILL BE CONDUCTING HYDROGRAPHIC  
SURVEY AND SOIL SAMPLING AT MANILA BAY FROM 16 JUNE 2018 TO 14 JULY  
2018 WITHIN THE AREAS BOUNDED BY THE FOLLOWING COORDINATES:**

#### AREA I

**POINT A: 14° 30.4'N., 120° 58.5'E.  
POINT B: 14° 31.1'N., 120° 57.2'E.  
POINT C: 14° 31.8'N., 120° 57.7'E.  
POINT D: 14° 33.0'N., 120° 57.4'E.  
POINT E: 14° 33.4'N., 120° 58.7'E.**

#### AREA II

**POINT A: 14° 28.217'N., 120° 45.810'E.  
POINT B: 14° 29.853'N., 120° 49.670'E.  
POINT C: 14° 27.254'N., 120° 52.112'E.  
POINT D: 14° 18.148'N., 120° 41.909'E.  
POINT E: 14° 17.059'N., 120° 39.680'E.  
POINT F: 14° 19.603'N., 120° 38.372'E.**

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE  
ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY  
PRECAUTIONARY MEASURES AT ALL TIMES.**

# IV

## NAVIGATIONAL WARNINGS

Date: 25 June 2018

Reference: PCG NTM 132 & 133-2018 (HD 138 & 139/18)

### MESSAGE

---

**NAVPHIL 077/18 – PHILIPPINE WATERS – TEST FIRING**

**THE PHILIPPINE NAVY VESSELS WILL CONDUCT TEST FIRING OF THEIR NAVAL GUNS ON THE DATES AND PLACES AS INDICATED:**

- A. PC393 AT VICINITY 5 NAUTICAL MILES NORTHWEST OFF PANGUTARAN ISLAND, SULU ON 30 JULY 2018 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 06° 28' 24"N., 120° 33' 48"E.  
POINT B: 06° 28' 24"N., 120° 36' 48"E.  
POINT C: 06° 31' 24"N., 120° 36' 48"E.  
POINT D: 06° 31' 24"N., 120° 33' 48"E.

- B. BRP GENERAL MARIANO ALVAREZ (PS38) AT VICINITY 8.7 NAUTICAL MILES EAST OFF MATANAL POINT, BASILAN ON 25 JULY 2018 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 06° 38' 45.42"N., 122° 28' 46.98"E.  
POINT B: 06° 33' 36.54"N., 122° 28' 46.98"E.  
POINT C: 06° 33' 38.16"N., 122° 33' 54.24"E.  
POINT D: 06° 38' 43.80"N., 122° 33' 57.48"E.

- C. BA487 AT VICINITY 10 NAUTICAL MILES SOUTH OFF CAPE SAN AGUSTIN, DAVAO ORIENTAL ON 03-05 JULY 2018 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 06° 06' 10.14"N., 126° 11' 40.08"E.  
POINT B: 06° 06' 12.96"N., 126° 12' 41.58"E.  
POINT C: 06° 05' 09.78"N., 126° 11' 40.5"E.  
POINT D: 06° 05' 09.24"N., 126° 12' 41.04"E.

**ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**



# IV

## NAVIGATIONAL WARNINGS

Date: 27 June 2018

Reference: PCG NTM 134 & 135-2018 (HD 143 & 144/18)

### MESSAGE

---

#### NAVPHIL 079/18 – PHILIPPINE WATERS – TEST FIRING

THE PHILIPPINE NAVY VESSELS WILL CONDUCT TEST FIRING OF THEIR NAVAL GUNS ON THE DATES AND PLACES AS INDICATED:

- A. BRP DIOSCORO PAPA (PC381) AT VICINITY 13.5 NAUTICAL MILES SOUTHEAST OFF SIBAGO ISLAND, BASILAN ON 06 JULY 2018 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A:      06° 40' 00"N., 122° 35' 00"E.  
POINT B:      06° 32' 00"N., 122° 35' 00"E.  
POINT C:      06° 40' 00"N., 122° 44' 00"E.  
POINT D:      06° 32' 00"N., 122° 44' 00"E.

- B. BRP ABRAHAM CAMPO (PC396) AT VICINITY 10.5 NAUTICAL MILES NORTH OFF GUINTACAN ISLAND, CEBU ON 09-13 JULY 2018 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A:      11° 34' 15"N., 123° 49' 18"E.  
POINT B:      11° 34' 15"N., 123° 55' 18"E.  
POINT C:      11° 28' 30"N., 123° 55' 12"E.  
POINT D:      11° 28' 30"N., 123° 49' 00"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

# IV

## NAVIGATIONAL WARNINGS

Date: 28 June 2018

Reference: PCG NTM 141-2018 (HD 148/18)

### MESSAGE

#### NAVPHIL 080/18 – LUZON W. COAST, LUZON SEA – BATHYMETRIC SURVEY

TRINAV SURVEYS INC., WILL CONDUCT BATHYMETRIC SURVEY IN BOTOLAN, CABANGAN AND SAN FELIPE IN ZAMBALES FROM 23 JUNE 2018 TO 23 JULY 2018 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

#### AREA 1

POINT	LATITUDE	LONGITUDE
1	15° 16' 42.09"N.	120° 00' 04.55"E.
2	15° 16' 04.99"N.	120° 00' 52.31"E.
3	15° 15' 54.59"N.	120° 00' 56.62"E.
4	15° 15' 42.14"N.	120° 00' 57.35"E.
5	15° 15' 12.76"N.	120° 00' 50.37"E.
6	15° 13' 31.65"N.	120° 00' 5.73"E.

#### AREA 2

POINT	LATITUDE	LONGITUDE
1	15° 07' 13.25"N.	120° 01' 13.76"E.
2	15° 06' 08.40"N.	120° 02' 58.98"E.
3	15° 05' 43.92"N.	120° 03' 03.18"E.
4	15° 04' 47.27"N.	120° 02' 34.65"E.

#### AREA 3

POINT	LATITUDE	LONGITUDE
1	15° 04' 05.07"N.	120° 02' 34.34"E.
2	15° 02' 39.23"N.	120° 03' 16.64"E.
3	15° 02' 10.19"N.	120° 03' 10.13"E.
4	15° 01' 52.33"N.	120° 03' 18.14"E.
5	15° 00' 03.60"N.	120° 02' 46.66"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

## **IV**

### **NAVIGATIONAL WARNINGS**

Date: 28 June 2018

Reference: PCG NTM 142-2018 (HD 149/18)

#### MESSAGE

**NAVPHIL 081/18 – LUZON W. COAST, MANILA BAY – GEOTECHNICAL INVESTIGATION**

**THE GEOTHECNICS PHIL. INC., WILL UNDERTAKE A GEOTECHNICAL INVESTIGATION WORKS FOR A PROPOSED MANILA BAY RECLAMATION PROJECT FROM 19 JUNE 2018 TO 30 SEPTEMBER 2018 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

<b>POSITIONS</b>	<b>LATITUDE</b>	<b>LONGITUDE</b>
<b>A</b>	<b>14° 34' 29.26"N.</b>	<b>120° 55' 56.91"E.</b>
<b>B</b>	<b>14° 33' 47.41"N.</b>	<b>120° 56' 36.88"E.</b>
<b>C</b>	<b>14° 34' 28.56"N.</b>	<b>120° 57' 19.49"E.</b>
<b>D</b>	<b>14° 35' 02.50"N.</b>	<b>120° 57' 31.60"E.</b>
<b>E</b>	<b>14° 35' 21.83"N.</b>	<b>120° 57' 06.77"E.</b>
<b>F</b>	<b>14° 34' 58.28"N.</b>	<b>120° 56' 37.46"E.</b>
<b>G</b>	<b>14° 34' 55.94"N.</b>	<b>120° 55' 56.56"E.</b>

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.**

**IV**  
**NAVIGATIONAL WARNINGS**

Date: 28 June 2018

Reference: Royal Cargo Letter (HD 153/18)

MESSAGE

**NAVPHIL 082/18 – LUZON, SW. COAST – VERDE ISLAND PASSAGE – PIPELINE  
INSPECTION**

**SHELL PHILIPPINE EXPLORATION (SPEX), UTILIZING FPV JOSEPH PLATEAU  
WILL BE WORKING AS THE ROCK INSTALLATION VESSEL FOR THE  
MALAMPAYA GAS EXPORT PIPELINE FROM 02 JULY 2018 TO 15 AUGUST 2018  
AT THE FOLLOWING COORDINATES:**

<b>POINT 1</b>	<b>13° 28.37'N., 121° 05.53'E.</b>
<b>POINT 2</b>	<b>13° 46.5'N., 121° 59'E.</b>
<b>POINT 3</b>	<b>13° 27.50'N., 121° 06.36'E.</b>
<b>POINT 4</b>	<b>13° 28.58'N., 121° 05.31'E.</b>

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS  
ARE ADVISED TO OBSERVE SAFE DISTANCE OF FIVE (5) NAUTICAL MILES  
FROM THE VESSEL AND TAKE NECESSARY PRECAUTIONARY MEASURES AT  
ALL TIMES.**

## **IV**

# **NAVIGATIONAL WARNINGS**

Date: 28 June 2018

Reference: Royal Cargo Letter (HD 153/18)

### MESSAGE

**NAVPHIL 082/18 – LUZON, SW. COAST – VERDE ISLAND PASSAGE – PIPELINE  
INSPECTION**

**SHELL PHILIPPINE EXPLORATION (SPEX), UTILIZING FPV JOSEPH PLATEAU  
WILL BE WORKING AS THE ROCK INSTALLATION VESSEL FOR THE  
MALAMPAYA GAS EXPORT PIPELINE FROM 02 JULY 2018 TO 15 AUGUST 2018  
AT THE FOLLOWING COORDINATES:**

<b>POINT 1</b>	<b>13° 28.37'N., 121° 05.53'E.</b>
<b>POINT 2</b>	<b>13° 46.5'N., 121° 59'E.</b>
<b>POINT 3</b>	<b>13° 27.50'N., 121° 06.36'E.</b>
<b>POINT 4</b>	<b>13° 28.58'N., 121° 05.31'E.</b>

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS  
ARE ADVISED TO OBSERVE SAFE DISTANCE OF FIVE (5) NAUTICAL MILES  
FROM THE VESSEL AND TAKE NECESSARY PRECAUTIONARY MEASURES AT  
ALL TIMES.**

## **V**

### **PUBLICATION NOTICES**

1. There is no publication notice for this month.

## REQUEST FOR CORRECTIVE INFORMATION

Mariners are requested to notify the **Hydrography Branch, NAMRIA** of any changes or discrepancies found on Charts published by this office especially if this affect navigational safety in Philippine Waters. Reports may be sent by facsimile (FAX No. (632) 242 20 90) or by speed mail to:

NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY  
Hydrography Branch  
421 Barraca Street, San Nicolas  
1010 Manila, Philippines  
Attention: Maritime Affairs Division

Reports may also be sent by electronic mail (e-mail) to:

[maritime.affairs@namria.gov.ph](mailto:maritime.affairs@namria.gov.ph)

*(Please send the information in format similar to that found at the back cover of this publication)*

# REPORT OF SIGHTING/DISCOVERY

General locality \_\_\_\_\_

Date \_\_\_\_\_ Time \_\_\_\_\_

Approximate Position: Latitude. \_\_\_\_\_ N.,

Longitude. \_\_\_\_\_ E.

Reference datum: \_\_\_\_\_

Position Determined by (Method/Instrument used):

\_\_\_\_\_

Nature/description of MSI (*Floating hazard, unlit light station, uncharted shoals, adrift vessels etc.*)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Weather/sea condition in the locality \_\_\_\_\_

MSI Reported by:

\_\_\_\_\_

\_\_\_\_\_

Master or Navigator

Vessels/Country Registry

Enroute to: \_\_\_\_\_

To: The Director  
Hydrography Branch  
421 Barraca Street, San Nicolas  
1010 Manila, PHILIPPINES  
Fax No. (632) 242-20-90  
E-mail: icsu\_hd@namria.gov.ph