

PHILIPPINE NOTICES TO MARINERS

Monthly Edition No.: 2025-01 31 January 2025

Notices Nos.: 001 to 003

CONTENTS

- Index of Charts Affected
- II Chart Corrections

L

- III Temporary & Preliminary Notices
- IV List of Lights Corrections
- V Coast Pilot Corrections
- VI Navigational Warnings
- VII Publication Notices

Published by National Mapping and Resource Information Authority Lawton Avenue, Fort Bonifacio, Taguig City

ISSN 3028 -1067

Tel: (632) 8241-3494 to 98 Email: csu.hb@namria.gov.ph (NAMRIA Client Service Unit) Website: www.namria.gov.ph

MARITIME AFFAIRS DIVISION

Maritime Spatial and Safety Information Service Editorial Board December 2024

Editor-In-Chief: LT MAY ANNE L JAVIER

Supervising Editor: ENS GEORGE L DIMEN JR

Verifier: HERMIELYN C. SAGUCIO Compilers: SN3 ANJANETTE A CRUCIS SN3 RHEAN MARK A MONILLA SN3 SAMUEL F SORIANO SN3 KRISHNA O LEE TERESITA B. SARMIENTO **THE PHILIPPINE NOTICES TO MARINERS** is a monthly publication produced by the National Mapping and Resource Information Authority (NAMRIA). It contains the recent chart corrections, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format may be obtained or by downloading at the NAMRIA website: https://namria.gov.ph/downloads.aspx#publications or by sending a request through the email address maritime.affairs@namria.gov.ph.

Organized chart corrections, cumulative and summary list of chart corrections as well as online hydrographic note are also available through the **Online Maritime Safety Information System** (OMSIS), https://isportal.namria.gov.ph/OMSIS/Default.aspx

Masters of vessels and other concerned parties are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots, which may come to their attention, to the *Director, Hydrography Branch*. If such information warrants urgent attention, for instance the non-existence of aids to navigation or failure of light beacons or similar structures or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:


Mail	NAMRIA Hydrography Branch,
	421 Barraca St San Nicolas, 1010 Manila, Philippines
E-mail	maritime.affairs@namria.gov.ph
Landline	(+632) 8245-0295
Online	https://namria.gov.ph/omsis/HNote10.aspx.

Active navigational warnings are accessible at https://staging.geoportal.gov.ph/nwapp/

EXPLANATORY NOTES

1. The Philippine Notices to Mariners is divided into the following sections:

Section I. Index of Charts Affected – Contains the list of all nautical charts which have been affected by Notices to Mariners and the Notice Numbers which have affected them.



Section II. Chart Corrections - Contains corrections to nautical charts in sequential numbers with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:

Notice No. preceded by an asterisk " * " indicates that the information is based upon the original Philippine source.

Section III. Temporary & Preliminary Notices – Contains Notices to Mariners that temporarily affect the nautical charts or have preliminary information that is subject to further verification. The capital "P" or "T" affixed in the number of any notice denotes "*preliminary*" or "temporary", respectively.

A list of Temporary and Preliminary Notices that are still in force is published in this publication every month. The list may be read on Page v.

Section IV. List of Lights Corrections – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contain updates will be denoted by an asterisk "*". All columns will be denoted by asterisks in the case of new lights.

This section is intended to be printed, cut out and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from True North 000° to 360°. Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance, and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should also be forwarded to the Commandant of the Philippine Coast Guard.

Section V. Coast Pilot Corrections – Contains the corrections to the latest editions of the Philippine Coast Pilot books.

Section VI. Navigational Warnings – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

Section VII. Publication Notices – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

- NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of the safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
- 3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that it may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard the ship and use a lookout during navigation.
- 4. Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some navigational lights. Buoys and beacons are sometimes lost or destroyed, especially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
- 5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that due to the age and quality of some of the information, such satellite-derived positions may be more accurate than charted details.

List of Temporary and Preliminary Notices

(in force as of 31 January 2025)

11(115)T/24 BATANES GROUP OF ISLANDS, Batan Island - Light 10(110)T/24 LUZON, W. Coast, Manila Bay – Wreck. Restricted Area 10(109)T/24 LUZON, W. Coast, Manila Bay – Buoy 10(108)T/24 DAVAO, NE. Coast, Pakiputan Strait – Buoys 09(101)P/24 LUZON, W. Coast, Zambales - Dredging 09(100)P/24 LUZON, W. Coast, Manila Bay – Reclamation 08(092)T/24 WEST PHILIPPINE SEA, Julian Felipe Reef - Buoys 08(091)T/24 LUZON, S. Coast, Odiongan Bay – Buoy 08(090)T/24 LEYTE, S. Coast, San Juan - Lights 08(089)T/24 LEYTE, N. Coast, Biliran I - Light 08(088)T/24 SAMAR, W. Coast - Lights 08(087)T/24 SAMAR, NE. Coast, Hiuinatungan I - Light 08(086)T/24 KALAYAAN ISLAND GROUP, Pag-asa Island - Buoy 07(074)T/24 PALAWAN, N. COAST, Cabuli I. - Light 07(073)T/24 LUZON, S. COAST, Sibuyan I - Lights 07(072)T/24 LUZON, NE. COAST - Lights 07(071)T/24 PHILIPPINE RISE, Benham Bank – Buoys 07(070)T/24 PALAWAN, N. COAST, Coron Passage - Buoys 07(069)T/24 LUZON, S. COAST, Sibuyan Island - Lights 07(068)T/24 LUZON, S. COAST, Laguna de Bay - Lights 07(067)T/24 LUZON, N. COAST, Batan Island - Light 07(066)T/24 LUZON, W. COAST, Manila Bay - Anchorage 07(065)T/24 LUZON, NE. COAST, Padsan River – Dredging 09(114)P/23 LUZON. S. COAST, Batangas Bay - Terminal 03(048)T/23 PALAWAN, E. COAST, off Miniloc Island – Buoy 03(047)T/23 BOHOL, W. COAST, Dawahon Bank - Light 02(032)T/23 PALAWAN, N. COAST, Coron Bay - Buoy 02(031)T/23 LUZON, W. COAST, Manila Bay – Buoy 01(020)T/23 LUZON, W. COAST, Manila Bay - Buoy 12(077)T/22 MASBATE, NORTH COAST, Masbate Harbor - Beacon 09(040)T/22 LUZON, W. COAST, Manila Bay – Buoy 07(032)T/22 LUZON, W. COAST, Manila Bay - Buoy 07(031)T/22 LUZON, W. COAST, Manila Bay - Buoy 05(022)T/22 LUZON, W. COAST, Manila Bay - Buoy 02(006)T/22 LUZON, W. COAST, Manila Bay - Buoys 04(023)P/19 MINDANAO, N. COAST, Iligan Bay – Buoy 02(014)P/17 MINDANAO, N. COAST, Butuan Bay - Submarine Pipeline

TABLE OF CONTENTS

Index of Charts Affected	01
Chart Corrections	02
Temporary & Preliminary Notices	04
List of Lights Corrections	05
Coast Pilot Corrections	06
Navigational Warnings	07
Publication Notices	09

Chart No	Notice No.						
1508	01(002)T/25	4276	01(002)T/25	4705	01(002)T/25	PH2CVZ40	01(003)P/25
1509	01(002)T/25	4446	01(003)P/25	4726A	01(002)T/25	PH2CMN40	01(001)T/25
1523	01(001)T/25	4447	01(003)P/25	5001	01(002)T/25	PH2NLZ40	01(002)T/25
4228	01(002)T/25	4624	01(001)T/25	5002	01(002)T/25	PH3BYNIS	01(002)T/25
4229	01(002)T/25	4656	01(001)T/25			PH3CPEGN	I 01(002)T/25
						PH4CBA40	01(003)P/25
						PH5CBH40	01(003)P/25
		l		l		l	

II CHART CORRECTIONS

No Chart Correction Notices for this month.

III TEMPORARY AND PRELIMINARY NOTICES

*01(001)T/25 – DAVAO, NE. Coast, Pakiputan Strait – Buoys

- 1. Construction of a bridge is taking place in Pakiputan Strait.
- 2. The following lateral light-buoys have been established to mark the channel for navigation:

Characteristics	Designation	Buoy Type	Position
FI.G.3s	NB-1	Port	07°06.20'N., 125°39.40'E.
FI.R.3s	NB-2	Starboard	07°06.17'N., 125°39.52'E.
Fl.G.3s	NB-3	Port	07°05.82'N., 125°39.43'E.
FI.R.3s	NB-4	Starboard	07°05.82'N., 125°39.30'E.

3. Mariners are advised to navigate with caution in the area.

4. Former Notice 10(108)T/24 is cancelled. (WGS-84 Datum)

Chart Affected: 1523, 4624, 4656 ENC Affected: PH2CMN40 (Philippine Coast Guard)

*01(002)T/25 - LUZON, N. Coast, Port San Vicente - Light

Port San Vicente Light, FI.R.5s, in position 18°30.62'N 122°08.51'E., is unlit. (WGS84 DATUM)

Chart Affected: 1508, 1509, 4228, 4229, 4276, 4705, 4726A, 5001, 5002 ENC Affected: PH2NLZ40, PH3BYNIS, PH3CPEGN (Philippine Coast Guard)

*01(003)P/25 – Cebu, E. Coast, Cebu Harbor - Dredged Area

1. A new dredged area, depth 10.66m (CPA, 2024), has been established bounded by the following positions:

10°18.60'N 123°55.53'E, 10°18.50'N 123°55.62'E, 10°18.51'N 123°55.64'E, 10°18.43'N 123°55.71'E, 10°18.24'N 123°55.47'E, 10°17.97'N 123°55.44'E, 10°17.98'N 123°55.39'E, 10°18.12'N 123°55.40'E, 10°18.34'N 123°55.21'E.

- 2. A turning circle has been established within the dredged area.
- 3. Pilotage are compulsory when entering the dredged area.
- Mariners are advised to navigate with caution in the area and consult Cebu Port Authority for the latest information. (WGS84 DATUM)

Charts Affected: 4446 and 4447 ENC Affected: PH2CVZ40, PH4CBA40, PH5CBH40 (Cebu Port Authority)

IV LIST OF LIGHTS CORRECTIONS

No List of Lights Corrections Notices for this month.

V COAST PILOT CORRECTIONS

No Coast Pilot Corrections Notices for this month.

VI NAVIGATIONAL WARNINGS

See all active Navigational Warnings at https://staging.geoportal.gov.ph/nwapp/

NAVPHIL 204/24

WEST PHILIPPINE SEA.

KALAYAAN ISLAND GROUP. CHART 4723A.

LIKAS ISLAND LIGHT 11-04.78N 115-01.33E, F2823.8, UNLIT.

NAVPHIL 227/24

MANILA BAY. CHART 1501. OIL SPILL RESPONSE OPERATIONS ONGOING. TEMPORARY EXCLUSION ZONE RADIUS FOUR MILES ESTABLISHED CENTERED ON 14-30.3N 120-40.5E. SHIPS ARE PROHIBITED FROM ENTERING OR REMAINING WITHIN THE ZONE. CONTACT PHILIPPINE COAST GUARD TO ENTER PROHIBITED AREA AND FOR UPDATED INFORMATION.

NAVPHIL 272/24

SAMAR SEA. CALBAYOG CITY. CHART 1539. LIGHTBUOYS 12-02.58N 124-35.45E AND 12-03.35N 124-35.75E UNLIT.

NAVPHIL 293/24

BUTUAN BAY. LA UNION PT, SW. CHART 1536. SUBMERGED MOORING BUOY REPORTED 09-04.29N 125-31.05E.

NAVPHIL 299/24.

LUZON SEA AND MANILA BAY. CHART 1501 AND 1502. DREDGING AND RECLAMATION ACTIVITIES BY MV AN DA KANG 689, 5,445.00 TONS, IN PROGRESS UNTIL 30 JUNE 2025 IN AREAS BOUNDED BY: A. DREDGING AREA 15-02.55N 120-02.71E 15-02.56N 120-03.35E 15-01.76N 120-03.38E 15-01.76N 120-02.73E, **B. RECLAMATION AREA** 14-33.23N 120-57.10E 14-33.28N 120-57.10E 14-33.24N 120-57.66E 14-33.23N 120-57.66E. CANCEL THIS MSG 01 JULY 25.

NAVPHIL 305/24

CALAMIAN GROUP. CORON PASSAGE. CHART 1553. PORT HAND LIGHTBUOY 11-59.30N 120-14.73E MISSING.

NAVPHIL 307/24 MANILA BAY. MANILA SOUTH HARBOR.

CHART 4243. LIGHTBUOY, NNSL 8, 14-34.26N 120-54.64E OFF STATION TO 14-34.28N 120-54.62E.

NAVPHIL 351/24.

LUZON SEA. PINGET I, W. CHART 1504. PINGET LIGHT, 17-41.33N 120-21.25E, F2715, UNLIT.

NAVPHIL 361/24

VERDE ISLAND PASSAGE. CAPE SANTIAGO. CHART 1564. CAPE SANTIAGO LIGHT, 13-46.32N 120-39.18E, F2614, UNLIT.

NAVPHIL 362/24

PHILIPPINE SEA. MINDANAO, E. CHART 2200. SUBMARINE CABLE REPAIRING WORKS BY C/S ILE DE BREHAT, IN PROGRESS UNTIL FURTHER NOTICE, IN VICINITY OF LINE JOINING: 08-21.00N 130-02.00E 08-33.00N 130-12.00E 08-45.00N 130-25.00E.

NAVPHIL 363/24

PALAWAN, E. GREEN ISLAND BAY. CHART 1562. BARBACAN LIGHT, 10-19.10N 119-21.01E, F2169.5, UNLIT.

NAVPHIL 386/24

MACAJALAR BAY. MACABALAN PORT. CHART 4646. MACABALAN LIGHT, 08-30.42N 124-39.70E, F2266, UNLIT.

NAVPHIL 002/25 CEBU HARBOUR.

CHART 4446. WRECK REPORTED 10-18.85N 123 56.22E.

VI NAVIGATIONAL WARNINGS

NAVPHIL 005/25 SAN MIGUEL BAY. CHART 1514. SCIENTIFIC OPERATIONS BY BARGE LA ROCHE, 463.00 TONS, MTUG BELOY, 58.30 TONS, AND MTUG ADMIRAL TYLER, 31.39 TONS, IN PROGRESS, UNTIL 31 MAR IN AREA BOUNDED BY: 13-52.32N 123-04.15E 13-53.41N 123-17.16E 13-50.34N 123-18.90E 13-48.49N 123-19.43E 13-46.52N 123-17.88E 13-44.42N 123-15.18E 13-43.66N 123-11.18E 13-44.17N 123-07.04E 13-46.42N 123-02.90E 13-49.10N 123-02.96E. CANCEL THIS MSG 01 APR 25.

NAVPHIL 007/25

MANILA BAY. CHART 1501. NAVAL FIRING EXERCISES IN PROGRESS UNTIL 21 FEB, IN AREA BOUND BY: 14-42.48N 120-36.48E, 14-43.64N 120-41.48E, 14-38.87N 120-43.34E, 14-37.79N 120-38.28E. CANCEL THIS MSG 22 FEB 25.

VII PUBLICATION NOTICES

There is no publication notice for this month.

NAMRIA BULLETIN

- 1. Mariners are requested to notify the Hydrography Branch, NAMRIA of any changes or discrepancies found on Nautical charts and Nautical publications issued by this office, especially if this affects navigational safety in Philippine Waters. The information may be sent using the Hydrographic Note found on https://namria.gov.ph/omsis/HNote10.aspx.
- 2. Clients may purchase maps, nautical charts, publications and other maritime products online through https://namria.gov.ph/eMapa.
- 3. Please be advised that effective in October 2023, in alignment with Civil Service Commission Memorandum Circular numbers 22, series of 2014 and 6, series of 2022, and in support of the Department of Energy's energy-efficiency initiatives, we are implementing remote-work practice for non-frontline personnel every Friday. Frontline personnel engaged in critical functions and services will maintain their onsite presence.
- 4. Frontline personnel can be reached through the following contact numbers: Taguig City, Fort Bonifacio Map Sales Office (MSO) (02) 8810-4831 to 42 at local 431, (02) 8810-5467, 0956 5587584, and 0915 2777903; San Nicolas, Manila MSO (02) 8245-9498, (02) 8241-3494 at local 117, 0966 8523814, and 0921 3627524; DENR-Visayas Avenue (MSO) 0999 6079193 and 0928 4497159; and Client Service Section css.gismb@namria.gov.ph and 02 88875466.

Nautical Charts, Topographic Maps, Tide and Current Tables, and related publications are available for sale at the NAMRIA Map Sales Offices (MSO). Nautical Charts can also be purchased online thru https://namria.gov.ph/eMapa/

Region	Address	MSO STAFF	Phone/Fax
Main	Lawton Avenue, Fort Andres Bonifacio, Taguig City	Michelle Ann M. Aguilar Ana Victoria A. Labor Marlon Y. Aguilar	(02) 8810-4831 to 42 loc 431 (02) 8810-5467 0956 5587584 0915 2777903
NCR	421 Barraca Street, San Nicolas, Binondo, Manila	SN3 Marilou B. Cinco Romeo B. Brizuela Mary Jane M. Montano	(02) 8245-9498 (02) 8241-3494 loc 117 0966 8523814
NCR	FMB Building DENR Compound, Visayas Avenue, Quezon City	Sherry Ann S. Perez Glenn M. De Jesus	0999 6079193 0928 4497159
I	DENR Government Center, Sevilla City, San Fernando, La Union	Ayessa A. Valencia	0905 3443202
II	DENR-Land Evaluation Party Building II, Brgy. Carig, Tuguegarao City	Rubilyn T. Pulpulaan	0917 6519625
111	DENR Compound, Diosdado, Macapagal Gov't. Center. Maipis City, San Fernando, Pampanga	Rosalina M. Libunao	0991 3509756
IVA	Provincial Planning and Development Office, Capitol Complex, Batangas City	Engr. Leda P. Velasquez	0961 4552583
IVB	DENR-PENRO Santa Monica, Puerto Princesa City	Juvy B. Sarmiento Corazon L. Zeñarosa	0916 203 8041
V	DENR-Operation/Survey Division, Rizal Street, Sagpon, Legaspi City, Albay	Isabelita T. Climaco	0906 3363033
VI	Manuel Lagunilla Bldg., DENR Compound, Parola, Iloilo City	Temporarily Closed	
VII	DENR-CENRO Building, Arellano Boulevard corner V. Sotto Street Pier 3, Cebu City	Melchor Togonon Renato B. Alcontin, Jr.	0922 7910372 0931 0010341 0961 4552579
VIII	DENR Compound, Santo Niño Extension, Tacloban City	Temporarily Closed	
IX	Pres. Corazon C. Aquino Regional Government Center, Balintawak, Pagadian City, Zamboanga Del Sur	Ednalyn C. Macahidhid	0955 5826075 0948 2943647
IX	DENR CENRO, West General Vicente Alvarez St., Zone 4, Zamboanga City	Annete P. Flores	0955 8928777
х	DENR Building Macabalan, Cagayan de Oro City, Misamis Oriental	Temporarily Closed	
XI	Kilometer 7, SPED Road, Bangkal, Davao City	Temporarily Closed	
XII	3rd Floor, DENR Building Land Evaluation Survey Section, Aurora Street, Barangay Zone IV Koronadal City, South Cotabato	Jeanyluz B. Bautista	0909 9324745
CARAGA	DENR - Land Management Services Building, Ambago, Butuan City, Agusan del Norte	Maricar E. Siega	0948 3619452