



PHILIPPINE NOTICES TO MARINERS

Edition No.: 07 31 July 2019

Notices Nos.: 047 to 051

CONTENTS

- I Index of Charts Affected
- II Notices to Mariners
- III Corrections to Nautical Publications
- IV Navigational Warnings
- V Publication Notices

Produced by the Hydrography Branch

Published by the
Department of Environment and Natural Resources

NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY

Notices to Mariners – Philippine edition are now on-line at http://www.namria.gov.ph/download.php

Subscription may be requested thru e-mail at icsu_hd@namria.gov.ph

THE PHILIPPINE NOTICES TO MARINERS is the monthly publication produced by the Hydrography Branch of the National Mapping and Resource Information Authority (NAMRIA). It contains the recent charts correction data, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format may be obtained by sending a request through e-mail address: oss@namria.gov.ph or by downloading at the NAMRIA website: www.namria.gov.ph/download.php.

Masters of vessels and other concerned are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots which may come to their attention to the *Director, Hydrography Branch*. If such information warrants urgent attention like for instance the non-existence of aids to navigation or failure of light beacons or similar structure or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:

Mail: NAMRIA-Hydrography Branch, 421 Barraca St., San Nicolas, 1010

Manila, Philippines

E-mail: maritime.affairs@namria.gov.ph

Fax: (+632) 242-2090


The Hydrographic Note form at the back cover page of this publication must be used in reporting information on dangers to navigation, lighted aids, and other features that should be included in the nautical charts.

Explanatory Notes

1. The Philippine Notices to Mariners is divided to following sections:

Section I. Index of Charts Affected – Contains the list of all nautical charts which have been affected by Notices to Mariners and the notice numbers which have affected them.

Section II-A. Notices to Mariners - Contains corrections to nautical charts in sequential number with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:



Notice No. preceded by asterisk " * " indicates that the information is based upon original Philippine source.

Section II-B. Temporary & Preliminary Notices – Contains Notices to Mariners that temporarily affects the nautical charts or have preliminary information that is subject to further verification. The capital "P" or "T" affixed in the number of any notice denotes "preliminary" or "temporary", respectively.

A list of Temporary and Preliminary Notices that are still in force, as well as those that are canceled, is published in this publication every month. The list may be read on page iv.

Section III-A. Corrections to List of Lights – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contains updates will be denoted by an asterisk " * ". All columns will be denoted by asterisks in the case of new lights.

This section is intended to be cut out and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from true the North 000° to 360° . Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should be forwarded to the Commandant of the Philippine Coast Guard.

Section III-B. Coast Pilot Corrections – Contains the corrections to the latest edition of the Philippine Coast Pilot book.

Section IV. Navigational Warnings – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

Section V. Publication Notices – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

- NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
- 3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that it may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard ship and use a lookout during navigation.
- 4. Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some navigational lights. Buoys and beacons are sometimes lost or destroyed specially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
- 5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that due to the age and quality of some of information, such satellite-derived positions may be more accurate than charted details.

List of Temporary and Preliminary Notices

(in force as of 31 July 2019)

05(036)P/19 – LUZON, W. COAST, Subic Bay – Buoy 04(023)P/19 – MINDANAO, N. COAST, Iligan Bay – Buoy 11(063)P/18 – LUZON, W. COAST, Subic Bay – Wreck 10(055)P/18 – LUZON, W. COAST, Manila Harbor – Wreck 06(033)P/18 – LUZON, W. COAST, San Fernando Harbor – Buoy 01(004)P/18 – SULU ARCHIPELAGO – Recommended Route 07(040)P/17 – MINDANAO, W. COAST, Moro Gulf – Recommended Route 02(014)P/17 – MINDANAO, N. COAST, Butuan Bay – Submarine Pipeline

TABLE OF CONTENTS

Index of Charts Affected 1
Notices to Mariners 2
Temporary & Preliminary Notices
List of Lights Corrections 11
Coast Pilot Corrections
Navigational Warnings 12
Publication Notices 24

I INDEX OF CHARTS AFFECTED

Chart No.	Notices Nos.	Chart No.	Notices Nos.
1520	07(049)19	4603	07(049)19
1544	07(047)19	4628	07(049)19
1545	07(047)19	4629	07(049)19
45.40	07/047)40	4705	07/050\40
1546	07(047)19	4705	07(050)19
1551	07/047)10	4706	07/047\10
1551	07(047)19	4700	07(047)19
1552	07(047)19	4707	07(047)19
1002	07(017)10	1707	07(017)10
4205	07(050)19	4708	07(047)19
	,		07(048)19
4305	07(047)19		07(049)19
4315	07(047)19	4714	07(047)19
	2=(2,4=),42		2=(2,1=),12
4316	07(047)19	4716	07(047)19
4247	07/047\40	4740	07/047\40
4317	07(047)19	4718	07(047)19
4340	07(047)19	4723	07(051)19
7070	07(047)19	7120	07(001)19
4351	07(047)19	4723A	07(051)19
	(- , -		(== , =
4415	07(047)19		

II NOTICES TO MARINERS

*07(047)19 – SULU SEA, Northern Part – Submarine Cable

Chart 1544 1Ed 02/02/2012 [WGS-84 Datum] Last NM 04(013)18 Insert ~~~~~ joining: 12° 15.00′ N., 120° 56.10′ E. (shore) 12° 21.30' N., 121° 03.20' E. (W border) Chart 1545 1Ed 02/02/2012 [WGS-84 Datum] Last NM 12(279)15 Insert joining: 10° 36.00′ N., 121° 05.00′ E. (W border) 10° 36.00′ N., 121° 21.90′ E. 10° 46.03' N., 121° 47.81' E. 10° 47.33' N., 121° 53.13' E. 10° 48.04' N., 121° 56.68' E. (shore) Chart 1546 1Ed 02/02/2012 [WGS-84 Datum] Last NM 06(045)19 joining: 10° 39.14' N., 121° 30.00' E. (W border) Insert 10° 46.03′ N., 121° 47.81′ E. 10° 47.33′ N., 121° 53.13′ E. 10° 48.04' N., 121° 56.68' E. (shore) Chart 1551 1Ed 02/29/2012 [WGS-84 Datum] Last NM 05(035)19 Insert joining: 10° 46.87' N., 120° 12.00' E. (W border) 10° 45.08' N., 120° 19.87' E. 10° 35.91' N., 120° 44.29' E. 10° 35.98' N., 121° 14.00' E. (E border) joining: 11° 05.70′ N., 120° 11.50′ E. (W border) 11° 08.30' N., 120° 20.00' E. 11° 16.10' N., 120° 22.70' E. 11° 45.80' N., 120° 42.10' E. 11° 50.60′ N., 120° 42.50′ E. 11° 51.50' N., 120° 45.50' E. 12° 01.30' N., 120° 53.90' E. 12° 02.00' N., 120° 54.01' E. (N border)

II NOTICES TO MARINERS

*07(047)19 - SULU SEA, Northern Part - Submarine Cable (continued)

Chart 1551 1Ed 02/29/2012 [WGS-84 Datum] Last NM 05(035)19 joining: 11° 59.80' N., 120° 14.00' E. (shore) 11° 55.50' N., 120° 25.40' E. 11° 50.60' N., 120° 42.50' E. Chart 1552 1Ed 02/29/2012 [WGS-84 Datum] Last NM 05(035)19 Insert ~~~~~ joining: 11° 45.28' N., 120° 41.76' E. (S border) 11° 45.80' N., 120° 42.10' E. 11° 50.60' N., 120° 42.50' E. 11° 51.50' N., 120° 45.50' E. 12° 01.30' N., 120° 53.90' E. 12° 15.00' N., 120° 56.10' E. 12° 21.30' N., 121° 03.20' E. (shore) joining: 11° 59.80' N., 120° 14.00' E. (shore) 11° 55.50' N., 120° 25.40' E. 11° 50.60' N., 120° 42.50' E. Chart 4305 2Ed 12/07/1992 [Luzon Datum] Last NM 05(027)19 joining: 11° 44.98' N., 120° 41.43' E. (S border) Insert 11° 45.88' N., 120° 42.01' E. 11° 50.68' N., 120° 42.41' E. 11° 51.58' N., 120° 45.41' E. 12° 01.38' N., 120° 53.81' E. 12° 15.08' N., 120° 56.01' E. 12° 21.38' N., 121° 03.12' E. (shore) joining: 11° 59.88' N., 120° 13.91' E. (shore) 11° 55.58' N., 120° 25.31' E. 11° 50.68' N., 120° 42.41' E. Chart 4315 1Ed 03/12/1962 Rev 06/11/1990 [Luzon Datum] Last NM 01(002)18 Insert ~~~~~ joining: 11° 08.38' N., 120° 19.91' E. (S border) 11° 16.18' N., 120° 22.61' E. (E border)

II NOTICES TO MARINERS

*07(047)19 - SULU SEA, Northern Part - Submarine Cable (continued)

Chart 4316 2Ed 12/13/1993 [Luzon Datum] Last NM 10(053)18 Insert joining: 10° 49.73′ N., 119° 31.10′ E. (shore) 10° 50.36' N., 119° 32.00' E. (E border) joining: 10° 49.78' N., 119° 31.01' E. (shore) 10° 50.66' N., 119° 32.03' E. (E border) Chart 4317 1Ed 03/10/1958 Rev 07/14/1980 [Luzon Datum] Last NM 05(027)17 Insert joining: 10° 49.73' N., 119° 31.10' E. (shore) 10° 50.83' N., 119° 32.66' E. 10° 51.45' N., 119° 34.12' E. 10° 54.43' N., 119° 36.53' E. 10° 54.97' N., 119° 37.14' E. 10° 55.42' N., 119° 39.38' E. 10° 55.17' N., 119° 40.51' E. 10° 53.94' N., 119° 42.84' E. 10° 52.30' N., 119° 43.87' E. 10° 51.85' N., 119° 44.49' E. 10° 50.95' N., 119° 54.26' E. 10° 47.83' N., 120° 07.99' E. (E border) joining: 10° 49.78' N., 119° 31.01' E. (shore) 10° 55.38' N., 119° 37.51' E. 10° 54.58' N., 119° 46.41' E. 11° 04.24' N., 120° 07.98' E. (E border) Chart 4340 1Ed 06/27/1939 Rev 03/05/1976 [Luzon Datum] Last NM 01(001)17 joining: 12° 17.30′ N., 120° 58.52′ E. (W border) Insert 12° 21.38' N., 121° 03.12' E. (shore) Chart 4351 2Ed 11/04/1994 [Luzon Datum] Last NM 05(035)19 joining: 11° 59.88' N., 120° 13.91' E. (shore) Insert 11° 55.58' N., 120° 25.31' E. 11° 55.38' N., 120° 26.00' E. (E border)

II NOTICES TO MARINERS

*07(047)19 - SULU SEA, Northern Part - Submarine Cable (continued)

Chart 4415 1Ed 03/31/1958 Rev 02/27/1989 [Luzon Datum] Last NM 09(208)15 joining: 10° 46.10′ N., 120° 47.72′ E. (W border) Insert 10° 47.40′ N., 120° 53.05′ E. 10° 48.12' N., 120° 56.59' E. (shore) Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 06(045)19 Insert joining: 10° 49.7′ N., 119° 31.2′ E. (shore) 10° 50.8' N., 119° 32.8' E. 10° 51.4′ N., 119° 34.2′ E. 10° 54.4' N., 119° 36.6' E. 10° 54.9' N., 119° 37.2' E. 10° 55.3' N., 119° 39.5' E. 10° 55.1' N., 119° 40.6' E. 10° 53.9' N., 119° 42.9' E. 10° 52.2' N., 119° 44.0' E. 10° 51.8' N., 119° 44.6' E. 10° 50.9' N., 119° 54.3' E. 10° 45.1′ N., 120° 19.9′ E. 10° 35.9' N., 120° 44.3' E. 10° 36.0' N., 121° 21.9' E. 10° 46.0' N., 121° 47.8' E. 10° 47.3' N., 121° 53.1' E. 10° 48.0' N., 121° 56.7' E. (shore) joining: 10° 49.7' N., 119° 31.1' E. (shore) 10° 55.3' N., 119° 37.6' E. 10° 54.5' N., 119° 46.5' E. 11° 05.7' N., 120° 11.5' E. 11° 08.3' N., 120° 20.0' E. 11° 16.1' N., 120° 22.7' E. 11° 45.8' N., 120° 42.1' E. 11° 50.6' N., 120° 42.5' E. 11° 51.5' N., 120° 45.5' E. 12° 01.3' N., 120° 53.9' E.

12° 15.0' N., 120° 56.1' E.

12° 21.3' N., 121° 03.2' E. (shore)

II NOTICES TO MARINERS

*07(047)19 – SULU SEA, Northern Part – Submarine Cable (continued)

Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 06(045)19 Insert joining: 11° 59.8' N., 120° 14.0' E. (shore) 11° 55.5' N., 120° 25.4' E. 11° 50.6' N., 120° 42.5' E. Chart 4707 2Ed 11/2010 [WGS-84 Datum] Last NM 03(011)19 Insert joining: 10° 49.7' N., 119° 31.2' E. (shore) 10° 50.8' N., 119° 32.8' E. 10° 51.4′ N., 119° 34.2′ E. 10° 54.4' N., 119° 36.6' E. 10° 54.9′ N., 119° 37.2′ E. 10° 55.3' N., 119° 39.5' E. 10° 55.1' N., 119° 40.6' E. 10° 53.9' N., 119° 42.9' E. 10° 52.2' N., 119° 44.0' E. 10° 51.8' N., 119° 44.6' E. 10° 50.9' N., 119° 54.3' E. 10° 45.1' N., 120° 19.9' E. 10° 35.9' N., 120° 44.3' E. 10° 36.0' N., 121° 21.9' E. 10° 46.0' N., 121° 47.8' E. 10° 47.3' N., 121° 53.1' E. 10° 48.0' N., 121° 56.7' E. (shore)

joining: 10° 49.7' N., 119° 31.1' E. (shore)

10° 55.3' N., 119° 37.6' E.

10° 54.5' N., 119° 46.5' E.

11° 05.7' N., 120° 11.5' E.

11° 08.3' N., 120° 20.0' E.

11° 16.1' N., 120° 22.7' E.

11° 45.8' N., 120° 42.1' E. (N border)

II NOTICES TO MARINERS

*07(047)19 - SULU SEA, Northern Part - Submarine Cable (continued)

Chart 4708 2Ed 11/2010 [WGS-84 Datum] Last NM 06(046)19 joining: 10° 36.0′ N., 121° 10.0′ E. (W border) Insert 10° 36.0' N., 121° 21.9' E. 10° 46.0' N., 121° 47.8' E. (N border) Chart 4714 1Ed 09/14/1959 Rev 03/31/1986 [Luzon Datum] Last NM 05(034)19 Insert joining: 11° 45.0' N., 120° 41.4' E. (S border) 11° 45.9' N., 120° 42.0' E. 11° 50.7' N., 120° 42.4' E. 11° 51.6' N., 120° 45.4' E. 12° 01.4' N., 120° 53.8' E. 12° 15.1' N., 120° 56.0' E. 12° 21.4' N., 121° 03.1' E. (shore) joining: 11° 59.9' N., 120° 13.9' E. (shore) 11° 55.6' N., 120° 25.3' E. 11° 50.7' N., 120° 42.4' E. Chart 4716 2Ed 03/12/1984 Rev 10/1986 [Luzon Datum] Last NM 10(053)18 joining: 10° 49.7' N., 119° 31.1' E. (shore) Insert 10° 50.8' N., 119° 32.7' E. 10° 51.4' N., 119° 34.1' E. 10° 54.4' N., 119° 36.5' E. 10° 55.0' N., 119° 37.1' E. 10° 55.4' N., 119° 39.4' E. 10° 55.2' N., 119° 40.5' E. 10° 53.9' N., 119° 42.8' E. 10° 52.3' N., 119° 43.9' E. 10° 51.8' N., 119° 44.5' E. 10° 51.0' N., 119° 54.3' E. 10° 49.0' N., 120° 03.0' E. (E border) joining: 10° 49.8' N., 119° 31.0' E. (shore) 10° 55.4' N., 119° 37.5' E. 10° 54.6' N., 119° 46.4' E. 11° 05.8' N., 120° 11.4' E. (E border)

II NOTICES TO MARINERS

*07(047)19 – SULU SEA, Northern Part – Submarine Cable (continued)

Chart 4718 1Ed 10/16/1971 Rev 11/24/1975 [Luzon Datum] Last NM 06(046)19

> 10° 46.1' N., 120° 47.7' E. 10° 47.4' N., 120° 53.0' E.

10° 48.1' N., 120° 56.6' E. (shore)

(PLDT & UK Notice No. 2523 of 2017; HD 204/19 & 205/19)

07(048)19 - MINDANAO, S. COAST, off Sarangani Is. - Depth

Chart 4708 2Ed 11/2010 [WGS-84 Datum] Last NM 07(047)19

Insert 574 at: 05° 11.1' N., 125° 41.5' E. (a)

Delete 1488 at: (a) above

(UK Notice No. 2471 of 2017; HD 205/19)

07(049)19 - MINDANAO, N. COAST, Hinatuan Passage - Depth

Chart 1520 1Ed 05/30/2019 [WGS-84 Datum]

Insert 14: Rep(2017) at: 09° 30.58' N., 125° 53.22' E. (a)

Delete 49 close NE of (a) above

Chart 4603 1Ed 09/22/1958 Rev 09/08/1975 [Luzon Datum] Last NM 08(041)18

Insert : 76: Rep(2017) at: 09° 30.66' N., 125° 53.13' E. (a)

Delete 22 close N of (a) above

17 close SW of (a) above

Chart 4628 1Ed 05/26/1958 Rev 07/26/1976 [Luzon Datum] Last NM 06(031)18

Insert :76: Rep(2017) at: 09° 30.66' N., 125° 53.13' E.

II NOTICES TO MARINERS

07(049)19 - MINDANAO, N. COAST, Hinatuan Passage - Depth. (continued)

Chart 4629 3Ed 12/05/1994 [Luzon Datum] Last NM 04(012)18

Insert 4. Rep(2017) at: 09° 30.66′ N., 125° 53.13′ E.

Chart 4708 2Ed 11/2010 [WGS-84 Datum] Last NM 07(048)19

Insert 14: Rep(2017) at: 09° 30.58' N., 125° 53.22' E. (a)

Delete 55 close NE of (a) above

(UK Notice No. 2554 of 2017; HD 205/19)

*07(050)19 - LUZON STRAIT, Batan Islands - Geographic Names

Chart 4205 1Ed 08/16/1968 Rev 01/09/1984 [Luzon Datum] Last NM 09(054)17

Replace	AMIANAN I	with	MAVULIS I	at: 21° 06.90' N., 121° 58.00' E.
	NORTH I	with	MISANGA I	at: 21° 04.10' N., 121° 54.90' E.
	MAYSANGA I	with	A'LI I	at: 20° 55.78' N., 121° 53.78' E.
	MABUDIS I	with	D'TAREM I	at: 20° 56.00' N., 121° 56.50' E.
	DIOGO I	with	DI'NEM I	at: 20° 42 40' N 121° 56 50' F

Chart 4705 3Ed 03/2010 [WGS84 Datum] Last NM 01(001)19

at: 21° 06.9' N., 121° 59.3' E. Replace Yami I with Mavulis I at: 21° 03.9' N., 121° 58.3' E. North I with Misanga I at: 20° 55.3' N., 121° 58.5' E. Mabudis I with D'tarem I Di'nem I at: 20° 42.6' N., 121° 58.1' E. Diogo I with

(Municipality of Itbayat; HD 197/19)

II NOTICES TO MARINERS

07(051)19 - SOUTH CHINA SEA - Depth

Chart 4723 1Ed 01/2008 [WGS-84 Datum] Last NM 04(020)19

Insert	94:	at: 11° 29.0'N., 109° 34.4'E. <i>(a)</i>
	113, and extend 200m contour E to enclose,	at: 11° 18.3'N., 109° 37.0'E.
	110	at: 11° 03.3'N., 109° 30.3'E. (b)
	131	at: 10° 57.2'N., 109° 28.7'E.
Delete	102	close N of (a) above
	126	close N of (b) above
Chart 4	1723A 2Ed 12/22/2018 [WGS-84 Datum] Last I	NM 05(026)19
Insert	94:	at: 11° 29.0'N., 109° 34.4'E. <i>(a)</i>
	113	at: 11° 18.3'N., 109° 37.0'E.
	110	at: 11° 03.3'N., 109° 30.3'E. (b)
	131	at: 10° 57.2'N., 109° 28.7'E. (c)
Delete	102	close N of (a) above
	113	close SW of (a) above
	126	close N of (b) above
	192	close S of (c) above
(UK No	otice No. 604 of 2019; HD 208/19)	

III LIST OF LIGHTS CORRECTIONS

		NAME (2) ALLEY	POSITION (3)	CHARACTERISTICS (4)	Elev(m) <i>(5)</i>	Range(NM) <i>(6)</i>	STRUCTURE (7)	REMARKS (8)
0000	F2823	MAVULIS (YÁMI)	21 07 04 N 121 56 51 E	FI W 5s	20	15	White metal post	Vis 200°- 310°(110°) In WGS-84 Datum
REGION IV-A	- CALABAE							
QUEZON	- CALADAI	NZON .						
0117	F2750	BALISCAN ISLAND	14 14 40 N 121 53 58 E	FI W 5s	17	12	White concrete column, 9	TE 2019 *
0690	F2747.67	BONGLIW	15 03 31 N 121 56 36 E	FI W 5s	6	10	Concrete	In WGS-84 Datum TE 2019 *
REGION IV-B - MIMAROPA ROMBLON								
0166	F2532	TUNGGO POINT	12 54 15 N 121 43 16 E	FIW 5s			Concrete	TE 2019 *
REGION VI – WESTERN VISAYAS GUIMARAS								
0839	F2326.6 *	JORDAN WHARF	10 40 03 N 122 35 19 E	FIR 5s			White tower	In WGS-84 Datum
NEGROS	NEGROS OCCIDENTAL							
0459	F2359	PULUPANDAN	10 31 15 N 122 47 40 E	FIR 5s			GRP	In WGS-84 Datum *

Note: Asterisk " * " indicates new information in the column above it.

IV

NAVIGATIONAL WARNINGS

Date: 23 March 2018

Reference: PCG NTM 062-2018 (HD 055/18)

MESSAGE

NAVPHIL 036/18 – LUZON, W. COAST, PASIG RIVER – CONSTRUCTION WORKS

DUMDUMA CONSTRUCTION AND TRADING CORP. IS CONSTRUCTING THE SAN JUAN RIVER VIADUCT FROM 05 MARCH 2018 TO 31 DECEMBER 2019 WITHIN THE VICINITY OF THE FOLLOWING COORDINATES:

14° 35' 26.63"N., 121° 00' 49.67"E. 14° 35' 23.39"N., 121° 00' 50.40"E. 14° 35' 23.15"N., 121° 00' 51.12"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 08 November 2018

Reference: PCG NTM 258-2018 (HD 288/18)

MESSAGE

NAVPHIL 173/18 - LUZON, W. COAST, PASIG RIVER - REHABILITATION

NAPINDAN HYDRAULIC CONTROL SYSTEM IS BEING REHABILITATED FROM 05 NOVEMBER 2018 TO 11 MARCH 2022 WITHIN THE VICINITY OF THE FOLLOWING COORDINATES:

14° 33' 28"N., 121° 04' 06"E. 14° 33' 26"N., 121° 04' 10"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 12 March 2019

Reference: PCG NTM 059-2019 (HD 056/19)

MESSAGE

NAVPHIL 026/19 – LUZON, W. COAST, PASIG RIVER – BRIDGE CONSTRUCTION

THE CHINA ROAD AND BRIDGE CORPORATION AND THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAY (DPWH) HAD AN ON-GOING BRIDGE CONSTRUCTION PROJECT ON DATES AND PLACES AS INDICATED:

A. VICINITY OF BINONDO – INTRAMUROS MANILA ALONG PASIG RIVER MARCH 2019 TO DECEMBER 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A: 14° 35′ 45.22″N., 120° 58′ 30.15″E. POINT B: 14° 35′ 45.20″N., 120° 58′ 28.35″E. POINT C: 14° 35′ 41.20″N., 120° 58′ 28.78″E. POINT D: 14° 35′ 41.41″N., 120° 58′ 30.28″E.

B. VICINITY OF MANDALUYONG AND MAKATI ESTRELLA – PANTALEON BRIDGE ALONG PASIG RIVER MARCH 2019 TO DECEMBER 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A: 14° 34′ 03.23″N., 121° 02′ 11.40″E.
POINT B: 14° 34′ 01.60″N., 121° 02′ 12.01″E.
POINT C: 14° 34′ 02.56″N., 121° 02′ 18.77″E.
POINT D: 14° 34′ 04.65″N., 121° 02′ 18.44″E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 11 June 2019

Reference: Blue Horizon Shipping Letter (HD 142/19)

MESSAGE

NAVPHIL 063/19 - LUZON, W. COAST, SISIMAN BAY - CONSTRUCTION WORK

BLUE HORIZON SHIPPING AND LOGISTIC SERVICES INC., IS CONSTRUCTING A COAL-FIRED POWER GENERATION FACILITY, UTILIZING DREDGER MAN YANG JUN 1, BARGE SAN HANG ZHUANG 16, SAN HANG BO 194 AND SAN HANG BO 191 AT BARANGAY ALAS-ASIN, MARIVELES, BATAAN FROM 05 JUNE 2019 TO 02 SEPTEMBER 2019 AT THIS POSITION:

14° 25' 01.18"N., 120° 32' 32.69"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 14 June 2019

Reference: PCG NTM 153-2019 (HD 147/19)

MESSAGE

NAVPHIL 067/19 - PHILIPPINE WATERS, NORTHERN PART - CABLE LAYING

BENLINE AGENCIES PHILIPPINES INC., UTILIZING "CS DEPENDABLE" IS CONDUCTING SUBMARINE CABLE LAYING IN NORTHERN PART OF THE PHILIPPINES WITH A DURATION OF SIX (6) MONTHS STARTING 08 JUNE 2019 TO 07 DECEMBER 2019 ALONG THE ROUTES DEFINED BY THE FOLLOWING POSITIONS:

SEGMENT 1

16° 35.9767'N., 120° 18.0467'E. 20° 52.2869'N., 117° 59.9991'E. 20° 01.9267'N., 119° 58.3931'E. 20° 11.6405'N., 123° 48.3331'E. 20° 17.8653'N., 123° 56.8457'E. 21° 15.2616'N., 127° 00.0000'E.

SEGMENT 2

21° 36.0026'N., 123° 56.5031'E. 20° 17.8653'N., 123° 56.8457'E. 20° 11.6405'N., 123° 48.3331'E. 15° 46.1059'N., 121° 33.8427'E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 17 June 2019

Reference: PCG NTM 158-2019 (HD 158/19)

MESSAGE

NAVPHIL 069/19 - LUZON W. COAST, MANILA BAY- DREDGING

BEN LINE AGENCY PHILIPPINES, INC., UTILIZING "CONGO RIVER" WILL CONDUCT DREDGING WORKS AT MANILA SOUTH HARBOR FAIRWAY FROM PIER 3 TO PIER 15 WITH A DURATION OF TWO (2) MONTHS FROM 20 JUNE 2019 TO 18 AUGUST 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT 1	14° 34.35512' N,	120° 57.33993' E.
POINT 2	14° 34.258434' N,	120° 57.418086' E.
POINT 3	14° 32.95767' N,	120° 56.317068' E.
POINT 4	14° 33.031950' N,	120° 56.23104' E.
POINT 5	14° 35.316396' N,	120° 57.883782' E.
POINT 6	14° 34.873182' N,	120° 58.308276' E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE-MENTIONED AREA ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.

Date: 15 July 2019

Reference: PCG NTM 190-2019 (HD 191/19)

MESSAGE

NAVPHIL 087/19 - LUZON, W. COAST, MANILA BAY - MARINE SEDIMENT SURVEY

SANDS MINING AND DEVELOPMENT CORPORATION IS CONDUCTING A MARINE SEDIMENT SURVEY OFF CAVITE FROM JULY – AUGUST 2019 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT 1: 14° 26' 19"N., 120° 46' 15"E. POINT 2: 14° 25' 27"N., 120° 47' 19"E. POINT 3: 14° 23' 18"N., 120° 44' 20"E. POINT 4: 14° 24' 06"N., 120° 43' 36"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 15 July 2019

Reference: PCG NTM 194-2019 (HD 192/19)

MESSAGE

NAVPHIL 088/19 - LUZON, W. COAST, MANILA BAY - INSTALLATION

WATERFRONT MANILA PREMIER DEVELOPMENT INC. WILL PUT UP WAVE OBSERVATION APPARATUS TO OBSERVE WAVE HEIGHT, WAVE PERIOD AND WAVE CURRENT FROM JULY 2019 TO 31 JULY 2020 AT THIS POSITION:

14° 33' 27"N., 120° 56' 48.6"E.

ALL SHIPS/WATERCRAFTS ARE ADVISED NOT TO ANCHOR OR TRAWL IN THE VICINITY OF THE ABOVE MENTIONED POSITION.

Date: 19 July 2019

Reference: PCG NTM 199-2019 (HD 196/19)

MESSAGE

NAVPHIL 089/19 - NEGROS, SW. COAST, SULU SEA - GUNNERY

THE PHILIPPINE NAVY (PN) AND ROYAL MALAYSIAN NAVY (RMN) WILL CONDUCT BILATERAL AND GUNNERY EXERCISE ON 07-08 AUGUST 2019 AT VICINITY 5 NAUTICAL MILES SOUTHWEST OFF CANSILAN POINT, NEGROS OCCIDENTAL AT THE FOLLOWING POSITIONS:

POINT A: 09° 41.00'N., 121° 54.00'E.
POINT B: 09° 14.00'N., 122° 48.00'E.
POINT C: 09° 21.00'N., 122° 21.00'E.
POINT D: 09° 47.50'N., 121° 27.00'E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 19 July 2019

Reference: PCG NTM200-2019 (HD 199/19)

MESSAGE

NAVPHIL 090/19 - LUZON, W. COAST, PAMPANGA BAY - GUNNERY

THE PHILIPPINE NAVY VESSELS OF 2ND PB DIV PB317, PB320, PB323 AND PB354 WILL CONDUCT TEST FIRING OF THEIR NAVAL GUNS ON 18 AUGUST 2019 AT VICINITY 9.8 NAUTICAL MILES NORTHWEST OFF LAMAO POINT, BATAAN IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A: 14° 43.4100'N., 120° 34.1735'E.
POINT B: 14° 46.7273'N., 120° 37.7520'E.
POINT C: 14° 39.0600'N., 120° 40.2400'E.
POINT D: 14° 41.6000'N., 120° 43.2000'E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 22 July 2019

Reference: PCG NTM 203-2019 (HD 200/19)

MESSAGE

NAVPHIL 091/19 - PHILIPPINE WATERS - GUNNERY

THE PHILIPPINE NAVY (PN) WILL CONDUCT TEST FIRING OF THEIR NAVAL GUNS ON DATES AND PLACES AS INDICATED:

A. BRP GEN MARIANO ALVAREZ (PS38) AT VICINITY 8.7 NAUTICAL MILES EAST OFF MATANAL POINT, BASILAN ON 05 AUGUST 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A: 06° 38.757'N., 122° 28.783'E. POINT B: 06° 33.609'N., 122° 28.837'E. POINT C: 06° 33.636'N., 122° 33.904'E. POINT D: 06° 38.730'N., 122° 33.958'E.

B. BRP JUAN MAGLUYAN (PC392) AT VICINITY 19.8 NAUTICAL MILES WEST OFF DULUNGIN POINT, SIOCON. ZAMBOANGA DEL NORTE ON 29-30 AUGUST 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A: 07° 47.900'N., 121° 45.000'E.
POINT B: 07° 41.700'N., 121° 45.000'E.
POINT C: 07° 41.700'N., 121° 38.900'E.
POINT D: 07° 47.900'N., 121° 38.900'E.

C. PB336 AT VICINITY 8 NAUTICAL MILES NORTHWEST OFF PANAMPALAN POINT, POLILLO ISLAND, QUEZON ON 15 AUGUST 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A: 15° 08.258'N., 121° 42.125'E.
POINT B: 15° 10.018'N., 121° 44.699'E.
POINT C: 15° 07.873'N., 121° 46.901'E.
POINT D: 15° 05.984'N., 121° 44.385'E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Date: 25 July 2019

Reference: PCG NTM 206 & 207-2019 (HD 201 & 202/19)

MESSAGE

NAVPHIL 092/19 - PHILIPPINE WATERS - GUNNERY

THE PHILIPPINE NAVY (PN) WILL CONDUCT TEST FIRING OF THEIR NAVAL GUNS ON DATES AND PLACES AS INDICATED:

C. BRP BONNY SERRANO (PC111) AT VICINITY 6.6 NAUTICAL MILES NORTHWEST OFF LUPAC POINT, MARINDUQUE ON 15-17 AUGUST 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A: 13° 30.09'N., 121° 42.57'E.
POINT B: 13° 30.05'N., 121° 34.19'E.
POINT C: 13° 37.62'N., 121° 35.52'E.
POINT D: 13° 38.11'N., 121° 43.51'E.

D. BRP ALFREDO PECKSON (PC372) AT VICINITY 8.7 NAUTICAL MILES NORTHEAST OFF MOLOCABOC ISLAND, ESCALANTE CITY, NEGROS OCCIDENTAL ON 23-24 SEPTEMBER 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A: 11° 01.51'N., 123° 43.24'E. POINT B: 11° 01.45'N., 123° 48.98'E. POINT C: 10° 56.12'N., 123° 48.61'E. POINT D: 10° 56.32'N., 123° 43.07'E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

V

PUBLICATION NOTICES

- **1.** There is no publication notice for this month.
- 2. Mariners are requested to notify the Hydrography Branch, NAMRIA of any changes or discrepancies found on nautical charts and nautical publications issued by this office especially if this affect navigational safety on Philippine Waters. Reported information may be sent using the Hydrographic Note or the Hydrographic Note for Port Information, which are on the succeeding pages.

Reports may be sent through the following means:

Mail: NAMRIA - Hydrography Branch, 421 Barraca St., San Nicolas, Manila 1010

Email: maritime.affairs@namria.gov.ph and maritime.concerns@gmail.com

Fax: (+632) 242-2955

NAMRIA HNC Form10 Rev00

HYDROGRAPHIC NOTE

Date	
Ref. No	
Name of ship or sender	IMO No
Address of sender	
Telephone/Mobile No	
Subject	
General locality	
Position: Latitude.	Longitude.
Position fixing system used	Datum
Charts affected	_ Edition
ENCs affected	
Latest Notice to Mariners held	
Nautical Publications affected (Edition No.)	
Details of anomaly or observation:	
A replacement copy of Chart Nois required (see Instruction 4). Signature of observer/reporter	
Tick box if not willing to be named as source of	f this information

INSTRUCTIONS

- Mariners are requested to notify the Hydrography Branch of the National Mapping and Resource Information Authority (NAMRIA) when new or suspected dangers to navigation are discovered, changes observed in aids to navigation, or corrections to publications that are seen to be necessary. Mariners can also report any ENC display issues experienced.
- 2. This form and its instructions have been designed to help both the sender and the recipient. It should be used, or followed, closely, whenever appropriate. Copies of this form may be obtained gratis from the Hydrography Branch at 421 Barraca St., San Nicolas, Manila, or by requesting thru email at maritime.affairs@namria.gov.ph.
- 3. Position: When a position is defined by sextant angles or bearings (true or magnetic being specified) more than two should be used in order to provide a check. Distances observed by radar should be quoted. However, when there is a series of fixes along a ship's course, only the method of fixing and the objects used need to be indicated. Latitude and longitude should only be used specifically to position the details when they have been fixed by astronomical observations or GPS and a full description of the method, equipment and datum used should be given.
- 4. Paper Charts: A cutting from the largest scale paper chart is the best medium for forwarding details, the alterations and additions being shown thereon in red. When requested, a new copy will be sent in replacement of a chart that has been used to forward information, or when extensive observations have involved defacement of the observer's chart. If it is preferred to show the amendments on a tracing of the largest scale chart (rather than the chart itself) these should be in red as above, but adequate detail from the chart must be traced in black ink to enable the amendments to be fitted correctly.

Electronic Navigational Charts (ENCs): A screen grab of the largest scale usage band ENC with the alterations and additions being shown thereon in red.

- 5. **Soundings:** When soundings are obtained, it is important to ensure that full details of the method of collection are included in this report. This include nut no limited to:
 - a. Make, model, and type of echo sounder used.
 - b. Whether the echo sounder is set to register depths below the surface or below the keel; in the latter case the vessel's draught should be given.
 - c. Time, date and time zone should be given in order that corrections for the height of the tide may be made where necessary, or a statement made as to what corrections for tide have already been made.
 - d. Where larger amounts of bathymetric data have been gathered, only those areas where a significant difference to the current chart or ENC should be specifically mentioned on the H102. The full data set may also be sent in, with an additional note added to this effect. If no significant differences are noted, the bathymetric data may still be of use, and sent in accordingly. Where full

data sets are included, a note as to the data owner and their willingness for the data to be incorporated into charts and ENCs included.

- 6. For Echo Sounders that use electronic 'range gating', care should be taken that the correct range scale and appropriate gate width are in use. Older electro-mechanical echo sounders frequently record signals from echoes received back after one or more rotations of the stylus have been completed. Thus, with a set whose maximum range is 500m, an echo recorded at 50m may be from depths of 50m, 550m or even 1050m. Soundings recorded beyond the set's nominal range can usually be recognized by the following:
 - a. the trace being weaker than normal for the depth recorded;
 - b. the trace passing through the transmission line;
 - c. the feathery nature of the trace.

As a check that apparently shoal soundings are not due to echoes received beyond the set's nominal range, soundings should be continued until reasonable agreement with charted soundings is reached. However, soundings received after one or more rotations of the stylus can still be useful and should be submitted if they show significant differences from charted depths.

- 7. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.
- 8. Changes to Port Information should be forwarded using Hydrographic Note for Port Information. Where there is insufficient space on the forms additional sheets should be used.
- Reports using this form and relevant data should be sent either through mail at NAMRIA-Hydrography Branch, 421 Barraca St., San Nicolas, Manila or through email at maritime.affairs@namria.gov.com and maritime.concerns@gmail.com.

An acknowledgement or receipt will be sent and the information then used to the best advantage which may mean immediate action or inclusion in a revision in due course; for these purposes, the NAMRIA-Hydrography Branch may make reproductions of any material supplied. When a Notice to Mariners is issued, the sender's ship or name is quoted as authority unless (as sometimes happens) the information is also received from other authorities or the sender states that they do not want to be named by using the appropriate tick box on the form. An explanation of the use made of contributions from all parts of the world would be too great a task and a further communication should only be expected when the information is of outstanding value or has unusual features.

NAMRIA HNC Form11 Rev00

HYDROGRAPHIC NOTE FOR PORT INFORMATION

Date:				
Name of Observer/Reporter:			IMO No	
Address of sender				
Telephone/Mobile No		E-mail		
Name of Port				
Approximate Position	Latitude		Longitude	
Port Authority Name and contact details				
General Remarks				
Principal activities and trade. Latest population figures and date.				
Number of ships or tonnage handled per year.				
Maximum size of vessel handled.				
Copy of Port Handbook (if available).				
Berthing Facility Type (L-pier, T-pier, wharf, etc.)				
Names, numbers or positions & lengths.				
Depths alongside.				
Storage Facility Area of open storage area and warehouse				
Existence of reefer facilities, cold storage, and special storage facilities.				
Anchorages Position, designation, depths, holding ground, shelter afforded.				

Pilotage Authority for requests.	
Pilot boarding position.	
Regulations (compulsory or not).	
Name of pilot association and contact details.	
Tugs Number available.	
Name of tug operator and contact details	
Directions Entry and berthing information.	
Tidal streams.	
Navigational aids.	
Small Craft Facility Name of yacht club, contact no., email address.	
Cargo Handling Containers, lighters, Ro-Ro etc.	
Repairs Hull, machinery and underwater.	
Shipyards.	
Docking or slipping facilities. (Give size of vessels handled or dimensions)	
Divers.	
Rescue and Distress Salvage, Lifeboat, Coastguard, etc.	
Name of nearest Coast Guard station and contact details.	
Supplies Fuel. (with type, quantities and methods of delivery)	
Fresh water. (with method of delivery and rate of supply)	
Provisions.	

Services Medical.	
Ship Sanitation.	
Garbage and slops.	
Ship chandlery, tank cleaning, compass adjustment, hull painting.	
Communications Nearest airport or airfield.	
Port radio and information service. (with frequencies and hours of operating)	
Government Services Customs	
Quarantine	
Plant and Animal Quarantine	
Immigration	
Local Situation Health facilities (nearest hospitals, clinics, health centers)	
Banks and money remittance facilities	
Views Photographs (where permitted) of the approaches, leading marks, the entrance to the harbor etc.	
Additional Details	
Signature of observer/reporter	

Notes:

- 1. This form lists the information required for Philippine Coast Pilot and has been designed to help the sender and the recipient. The sections should be used as an aide-memoir, being used or followed closely, whenever appropriate. Where there is insufficient space on the form an additional sheet should be used.
- 2. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.



Nautical Charts, Topographic Maps, Tide and Current Tables and related publications are available for sale at the following NAMRIA Map Sales Offices (MSO):

METRO MANILA:

NAMRIA Main Office MSO

Fort Andres Bonifacio, Taguig City Contact Nos. (02) 810-4831 to 42 local 431, (02) 810-5467

Manila MSO

Hydrography Branch 421 Barraca Street, San Nicolas, Manila Contact Nos. (02) 241-3494 to 96 local 117, (02) 245-9498

DENR Central Office MSO

Forest Management Bureau (FMB) Compound Visayas Avenue, Quezon City Contact Nos. (02) 925-1157

REGION I:

San Fernando (La Union) MSO

DENR Government Center Sevilla, San Fernando City Contact Nos. (0999) 405-6917

REGION II:

Cagayan MSO

DENR – LEP, Building II Carig, Tuguegarao City Contact Nos. (0999) 309-3702

CORDILLERA ADMINISTRATIVE REGION:

Baguio City MSO

Cottage I Forester Compound, PACDAL, Baguio City Contact Nos. (074) 442-5429, (074) 442-4531, 0918-9203590

REGION III:

Nueva Ecija MSO

GIS Room, WMRC Building, Central Luzon State University Compound Maharlika Highway, Muñoz City Contact Nos. (044) 456-0690, 0917-9313827

Pampanga MSO

Diosdado Macapagal Government Center Maimpis, San Fernando City Contact Nos. (0910) 372-5623

REGION IV-A:

Southern Tagalog MSO

Provincial Planning and Development Office Laurel Park, Capitol Site, Batangas City Contact Nos. (0905) 506-8681

REGION IV-B:

Puerto Princesa MSO

DENR-PENRO Compound, Brgy. Santa Monica, Puerto Princesa City Contact Nos. (048) 433-1391, (0918) 283-7045

REGION V:

Legazpi City MSO

DENR-Operation/Survey Division, Rizal St., Sagpon, Legazpi City Contact Nos. (052) 480-9825, (0920) 437-8877

REGION VI:

Iloilo City MSO

Manuel Lagunilla Bldg, DENR Compound, Parola, Iloilo City Contact Nos. (0919) 887-3862,

REGION VII:

Cebu City MSO

Room 301, Osmeña Bldg. II, Osmeña Blvd, Cebu City Contact Nos. (032) 505-9945, (0922) 791-0372

REGION VIII:

Tacloban City MSO

DENR Compound, Sto. Niño Extension, Tacloban City Contact Nos. (053) 325-6223, (053) 321-3386, 0921-3628489

REGION IX:

Zamboanga City MSO

DENR CENRO West

General Vicente Alvarez St., Zone 4, Zamboanga City Contact Nos. 0935-8609439

Zamboanga del Sur MSO

Pres. Corazon C. Aquino Regional Government, Center, Balintawak, Pagadian City, Zamboanga del Sur Contact Nos. 0907-2777422

REGION X:

Cagayan de Oro City MSO

Day Care Center Building, DENR-Compound, Macabalan (Puntod), Cagayan de Oro City Contact Nos. 0926-4148976

REGION XI:

Davao City MSO

Kilometer 7, SPED Road, Bangkal, Davao City Contact Nos. 0915-6127770

REGION XII:

Koronadal City MSO

DENR Region 12, Land Evaluation Party Ofice, Aurora Street, Koronadal City, South Cotabato Contact Nos. 0908-5459367, 0998-9840921

CARAGA Administrative Region:

CARAGA MSO

DENR Land Management Services Bldg., Ambago, Butuan City, Agusan del Norte Contact Nos. (085) 342-6124, (085) 341-3250, 0948-620-9442, 0926-683-5521